

*Hyd fluid  
GEN-76-17*

*29MAY 0405*

RATUZEXH HULNNAC2446 130030Z-UUUU-ARLMDTA;  
ZNR UUUUU  
R 290300Z MAY 76 ZEX  
FM ARNG-OAC EDGEWOOD MD//OAC-AVN-L//*ARMY*  
TO AIG 7401  
INFO CNGS WASH DC//MAB-ARL-A//  
R 261300Z MAY 76 ZEX  
FM CDR USAAVSOPM STL MO//DRSAV-FEG//  
TO AIG 8881

BT  
UNCLAS  
NOTE GLN THIS MESSAGE HAS NOT, REPEAT, HAS NOT BEEN TRANSMITTED TO  
UNITS SUBORDINATE TO ADDRESSEES; ADDRESSEES ARE RESPONSIBLE  
FOR DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS,  
ACTIVITIES, ELEMENTS, OR FOREIGN USERS AFFECTED OR CONCERNED;  
RETRANSMITTAL SHALL REFERENCE THIS MESSAGE;  
SUBJ: MAINTENANCE ADVISORY MESSAGE ON HYDRAULIC FLUID; NSN

PAGE 2 RUMTFFA4533 UNCLAS  
9150-88-223-4134 CONTRACT DSA-688-73-C-1509,  
ROYAL LUBRICANTS, BATCH/LOT 93, DUP MAY 76, MIL-H-5686  
(GEN-76-17)

1, DDCS RICH VA REPORTED CARTONS MARKED AS SUBJ PRODUCT WERE FOUND  
TO BE FILLED WITH CANS MARKED AS MIL-H-5686C HYDRAULIC FLUID,  
2, REQUEST ALL ARMY ACTIVITIES UNDER YOUR COMMAND BE NOTIFIED  
TO INSPECT ALL CARTONS MARKED AS FOLLOWS GLN  
HYDRAULIC FLUID, NSN 9150-88-223-4134, CONTRACT DSA 688-73-C-  
1509, ROYAL LUBRICANTS, BATCH/LOT 93, DUP MAY 76, MIL-H-5686;  
CARTONS SO MARKED SHOULD BE INSPECTED TO DETERMINE IF THEY ARE  
PACKED WITH CANS OF THE SUBJECT MIL-H-5686 FLUID, IF CARTONS ARE  
FOUND WHICH CONTAIN OTHER THAN THE MIL-H-5686 FLUID THEY SHOULD  
BE SEGREGATED, REPORT BY 1 JUL 76 TODDSC, RICH, VA  
HNDGSC-60SD//WITH INFO COPY TO USAGMPA//STSGP-ET//  
LOCATIONS  
AND NUMBER OF CARTONS FOUND TO CONTAIN MIL-H-5686C FLUID;  
NEGATIVE REPLIES ARE NOT REQUIRED,  
3, POINT OF CONTACT, MR, FORSTER, USAGMPA//STSGP-ET//NCAD, PA  
AV977-6853;  
BT  
#2446

*(m)*

*73*