

ARMY

CTUZEXW RULNNAC1637 1682375-0000--RUWMDTA;

NR 00000

172247Z JUN 81 ZEX

M ARNG DAC EA APG MD//NOB-AVN-L//

O AIG 7421

A-BWCSVD

171850Z JUN 81

M CDRTSARCOM STL MD //DRSTS-MEA//

O AIG 8881

IG 7515

UCLRFA/US ENV PROT AGY PO BOX 15027 LAS VEGAS NV

UCLRFA/US ENV PROT AGY REGION II 20 FEDERAL PLAZA NY NY

UEOCMA/NATIONAL OCEANIC AND ATMOSPHERIC ADM ROCKVILLE MD

/NOAA/A82 COL L A HEAVER//

UEVHFP/NASA KENNEDY SPACE CENTER CAPE CANAVERAL FL

/SI-SAT-23//

NFO AIG 9004

IG 7514

UCLEUA/CDRUSAAYNCS FT RUCKER AL //ATZO-DI//

UDMAD/USDAO TELAVIV ISRAEL

UF TA/CJUSMAG MAAG MADRID SPAIN //ARMY/NAV SEC//

UEHC/AIT WASH DC

A-BWCSVD

T

NCLAS

UBJ - SAFETY OF FLIGHT, MAINTENANCE NOTICE, MESSAGE RCS 090[D-1868]

H-1 STABILIZER BAR TUBE (NSN 1615-20-169-5085, P/N 204-011-328-11)

UH-1-8  
Stabilizer  
P/N 204

AGE 02 RUCIFRA6345 UNCLAS

INSTALLATION AND INSPECTION (UH-1-81-07)

USPENSE - NOT APPLICABLE

NOTE - THIS IS A SAFETY OF FLIGHT, MAINTENANCE NOTICE, MESSAGE RELEASED IN ACCORDANCE WITH AR 95-18 DATED 1 MAY 1980 AND HAS NOT

BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES; ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE

TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED, THE RETRANSMITTAL SHALL REFERENCE THIS MESSAGE.

FORSCOM MSG, 261830Z MAY 81, SUBJ - UH-1 STABILIZER BAR TUBE

INSTALLATION, (NOTAL)

REF A ADVISED ACTION ADDRESSEES TO INSPECT STABILIZER BAR

TUBES FOR INTERNAL CORROSION AND PROPER INSTALLATION.

THIS TSARCOM MESSAGE IS TO PROVIDE ADDITIONAL INFORMATION TO

ALL CONCERNED.

TM 55-1520-210-23, PARA 5-45B, PAGE 5-64 STATES THAT STABILIZER

BAR TUBES WILL BE INSTALLED WITH KEYWAY FACING DOWNWARD. TSARCOM

RECOMMENDS THAT ALL STABILIZER BAR TUBES BE INSPECTED AND KEYWAY

BE INSTALLED IN DOWNWARD POSITION AT NEXT PHASE INSPECTION.

(E)

4, INSPECTION FOR INTERNAL CORROSION IS NOT PRACTICAL; TUBES HAVE BEEN ASSIGNED A FIVE (5) YEAR CALENDAR LIFE TO ALLOW FOR CORROSION

PAGE 03 RUC:FRA6345 UNCLAS

BUILDUP; THEREFORE, EVIDENCE OF INTERNAL CORROSION DOES NOT MAKE STABILIZER BAR TUBE UNSERVICEABLE.

5, NON-DESTRUCTIVE TESTING AND INSPECTION = NOT REQUIRED,

6, STATUS ACCOUNTING = NOT REQUIRED;

7, DISPOSAL OF HAZARDOUS MATERIAL = NOT APPLICABLE,

8, TAMMS FORMS = NOT APPLICABLE;

9, FOREIGN MILITARY SALES (FMS)/INTERNATIONAL LOGISTICS RECIPIENTS DESIRING CLARIFICATION OF THIS MESSAGE SHOULD CONTACT CW4 JIM CRONIN,

TSARCOM, DRSTS=I, AUTOVON 693-2106 OR COMMERCIAL 314-263-2106;

10, TSARCOM TECHNICAL POINT OF CONTACT IS MR. RAY BOLAND, DRSTS=MEA, AUTOVON 693-3300, COMMERCIAL 314-263-3300;

BT

#1637

NNNN