

Cushion for Cover

WHAT'S
TH' MATTER
WITH HIM?



GRRRR



GRRMMP
GRUMBLE



OH--
HE GOT
BUMPED
OFF HIS
FLIGHT!

Dear Windy,

Some of our UH-1's are coming thru with rubber bumpers on the tail boom to provide a cushion for the tail rotor drive shaft cover.

Compared to the fragile anti-chafing tape we normally use, the bumpers do a much better job of preventing metal-to-metal contact between the cover and tail boom.

When a bumper does wear out, tho, what's the stock number for a replacement, Windy?

SP6 K. F.

TM 55-1520-210-23P ON THE HUEY IS BEING UPDATED TO INCLUDE THE RUBBER BUMPERS, NSN 5340-01-054-1588!

55

