P/01-100-292-02 BOLT

CTUZEXW RULNETC0066 0701941-UUUU--RUWMDTA. NR UUUUUU ARNG DAC EDGEWOOD AREA APG MD //NGB-AVN-L// 10 7375 271850Z MAR 80 CDRTSARCOM STL MO //DRSTS=SAJT// A1G 8879 NCLAS ORITICAL SHORT SUPPLY OF BOLT, EXTERNALLY RELIEVED, NSN ARMY DEPOT, CCAD IS NOT CONSIDERED C AT TSAROOM IS MRS. JUDY SCHNEIDER, AUTOVON 693-3653; 0955 ENGINE message 101902 X man 1980

NNN

CTUZEXW RULNETC#060 0701725-UUUU--RUWMDTA. NR UUUUU 101515Z MAR 80 ZEX M ARNG CAC EDGEWOOD AREA APG MD //NGB=AVN=L// O. AIG 7401 2313382 MAR 68 M CDRTSARCOM STL MO //DRSTS-SJAT// O A1G 8879 NCLAS UBJ - CRITICAL SHORT SUPPLY OF BOLT, EXTERNALLY RELIEVED, NSN ARNORMALLY HIGH USEAGE RAT OF SUBJECT BOLT AT OVERHAUL AND TOGETHER WITH MANUFACTURER'S INABILITY TO SUPPORT N A TIMELY MANNER HAS DEPLETED WHOLESALE STOCK, BOLT IS USED IN -53-L-13B/703/701A ENGINES ON UH-1/AR-1/0V-1 AIRCRAFT: . IN ORDER TO PRECLUDE AIRCRAFT DOWNTIME, IT IS ESSENTIAL THAT AXIMUM RE-USE OF BOLTS BE MADE DURING THE NEXT MINE MONTHS, REFER D MAINTANDE MANUAL TH 55-2840-229-24, PAGE 7-15, FOR PROPER NS STION CRITERIA. THERE HAS NEVER BEEN A MANDATORY REPLACEMENT F ALL SIX BOLTS: . REQUEST FIELD REQUIREMENTS BE REVIEWED FOR POSSIBLE CANCELLATION F REQUISITIONS REFLECTED AS DUE IN FROM TSARCOM AND ANY EXCESS TO

AGE 2 RULNETORROW UNCLAS
TATION REQUIREMENTS BE RETURNED TO THE NEAREST DEPOT WITH FULLI
REDIT GIVEN TO SATISFY NORS REQUISITIONS.
POC AT TSARCOM IS MRS. JUDY SCHNEIDER, AUTOVON 693-3653;

Message ENGINE 1015152 mar 1980 P/N1-100-292-02 shortage in se

INNN