

UH-1 S & S Nut

If the retaining nut on your Huey's scissor and sleeve assembly, Item 33 of Fig 5-44 of TM 55-1520-210-23-1, won't stay tight, check to see if you're using the correct torque. Change 15 to the TM changed the torque from 150-200 lb-ft to 200-250 lb-ft.