

Use an inspection mirror to eyeball the flexible-plate main drive shaft during the PM Daily, Huey mechs. The added check is for birds with the new Kamatics Kaflex drive shaft. TSARCOM Msg DRSTS-MEA 101745Z Apr 81 (UH-1-81-05) has details.

Look for broken or missing bolts, misalinement of plates at the connecting bolt points, and clamp security.

