

UH-1-75-16  
pilot/static system  
C. y. 1/14

RTTUZEXN RUEDAOA0349 3872183-0000--RUMMTA,  
ZNR 00000  
R 032026Z NOV 75 ZEX  
FM ARNG OAC EDGERWOOD ND //OAC-AVH-L//  
TO AIG 7401  
INFO RUEFHQA/CNCR WASHDC //HGB-ARL-A//  
P R 302045Z OCT 75  
FM CDRAVSCOM STL ND  
TO AIG 8581  
INFO AIG 9004  
CDRUSASPA FT WORTH TX  
CDR USASFSCOM HUNTSVILLE AL  
CDR USAAVCN FT RUCKER AL  
BT

UNCLAS

NOTE CLN THIS IS A MAINTENANCE ADVISORY MESSAGE AND HAS NOT, REPEAT,  
HAS NOT, BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES.  
ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL  
SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED,  
THE RETRANSMITTAL SHALL REFERENCE THIS MESSAGE.

SURJ CLN PERIODIC INSPECTION OF THE PILOT-STATIC SYSTEM (UH-1-75-16)

SUMMARY OF PROBLEM CLN THERE EXISTS THE POSSIBILITY OF OVER-  
PRESSURIZING THE PILOT/STATIC SYSTEM AND DESTROYING THE ASSOCIATED

PAGE 2 RUEDAOA0349 UNCLAS

INSTRUMENTATION BY FOLLOWING TM 55-1520-218-PMS SEQUENCE 1.6 AND  
1.7 AS WRITTEN (DATED 22 SEP 75),  
2. YOU ARE HEREBY REQUESTED TO MAKE THE FOLLOWING PEN AND INK  
CHANGES TO TM 55-1520-218-PMS SEQUENCE 1.6 AND 1.7 PENDING RECEIPT  
OF FORMAL MANUAL CHANGE CLN  
1.6 DISCONNECT PILOT/STATIC LINES FROM INSTRUMENTS AND CAP  
INSTRUMENT PORTS, REMOVE DRAIN CAPS FROM MOISTURE TRAPS,  
1.7 PURGE PILOT/STATIC SYSTEM WITH CLEAN, DRY, HIGH-PRESSURE  
AIR, RECONNECT LINES AND CAPS AND INSPECT LINES FOR LEAKS  
UTILIZING INSTRUMENT TEST SET,  
BT  
#0349