

PRIORITY

PCV MSG 8 TIME RADA  
38375 0107 117/a-  
2200MV 340TH 453FTS NAVY AERO COMM DPC DPM CORSEC LGT ACF ACD OSI NCAN CAP DOOC  
DOJ AUDITOR 4CAF ADC JA D0TH DOOS SSF SS  
D ACE DET T/A FTW/CC ABG/CC MA XPR LCS SE UEA PA W/DD XPMT LCC FCS SG OT

PCUZEKX RULNEA0952 1170050-0000--RUMHDTA.  
ZHR 00000.

P 252352Z APR 84 ZEX  
FM ARNG OAC AFG MD //HGB-AVN-L//

TO AIG 7401  
RULGTER/YI CHRISTIANSTED ST CROIX VI  
ACCT DA-BHCSVD

ARMY AM

P 252015Z APR 84  
FM CDRAVSCOM STL MO //DRSAV-N//

TO AIG 88A1  
RUCLEPA/US EVN PROT AGY PO BOX 15027 LAS VEGAS NV  
RUEVDRE/US EVN PROT AGY REGION II 20 FEDERAL PLAZA NY NY  
RUEOLNA/NATIONAL OCEANIC AND ATMOSPHERIC ADM ROCKVILLE MD  
//A00A/A02 COL L. A. WEAVER//  
RUEVHFP/NASA KENNEDY SPACE CENTER CAPE CANAVERAL FL  
//SI-SAT-23//

RUEHIN/AIT TAIPEI  
RUEHC/AIT WASH DC  
RUEHSH/COMUSMILGP SAN SALVADOR EL SALVADOR //SCES-AF//  
RUEBDG/COMUSMILGP BOGOTA COLUMBIA //SCCD-AFDCH//  
RUCDGD/REDSTONE ARSENAL AL //DRSHI-ST//  
RUEVHAD/US CUSTOMS SERVICE DEPT OF TREASURY  
RUCJAAA/CDR US REDCOM MC01LL AFB FL //RCCS-AVN//  
INFO AIG 9004

G 7515  
RUCLEPA/CDRUSAAVNC FT RUCKER AL //ATZQ-DI//  
RUCMAD/USDAO TEL AVIV ISRAEL

PAGE 02 RUCIFRD UNCLAS  
RUEHC/SEC STATE WASH DC //HEA/RF0//  
RUEHRO/ANEMB ROME ITALY //ODC//  
RUEOPHA/DISC PHILADELPHIA PA //OEBB-JU//  
RUCJAAA/USCINCPAC MACDILL AFB FL //RCCS-AVN//

*m/r mast  
then walk  
UH-1-84-04*

RUEHBT/CJUSMAGTHAI BANGKOK THAILAND  
RUFLEPA/CJUSMAG MAAG MADRID SPAIN //ARMY/NAVY SEC//  
RAYAAC/HQSCENG MELBOURNE AUSTRALIA //SOAIR ENG//  
RAYWPP/DEFAIR CANBERRA AUSTRALIA //OPHEL-AF//  
RUEVDEE/USDA FOREST SERVICE PO BOX 2417 WASH DC 20013  
//COOPERATIVE FIRE PROTECTION//  
ACCT DA-BHCSVD

BT  
UNCLAS  
SECTION 01 OF 02  
SUBJECT - SAFETY OF FLIGHT MAINTENANCE MANDATORY MESSAGE, ONE TIME  
INSPECTION OF UH-1 THMS 241D REPORTING SYSTEM CONCERNING UH-1 ROTOR  
WACT ASSEMBLY VERIFICATION (UH-1-84-04)  
NOTE - THIS IS A SAFETY OF FLIGHT, MAINTENANCE MANDATORY, ONE TIME  
INSPECTION MESSAGE. RELEASED IN ACCORDANCE WITH AR 95-18, DATED 1 MAY  
1980 AND HAS NOT, REPEAT, HAS NOT BEEN TRANSMITTED TO UNITS  
SUBORDINATE TO ADDRESSEES. ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT

*SOF-4*

PAGE 03 RUCIFRD7083 UNCLAS

THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OF CONCERNED. THE RETRANSMITTAL SHALL REFERENCE THIS MESSAGE. ACTION ADDRESSEES WILL IMMEDIATELY VERIFY THIS

TRANSMISSION TO COMMANDER, AVSCOM, ATTN - DRSAV-MPSD.

SUMMARY - IN 1978 THE ARMY INITIATED, ON AN ATTRITION BASIS, A CHANGE OUT OF THE THIN WALL MASTS (NSN 1615-00-073-8203), (P/N 204-040-366-9) TO THE THICK WALL MASTS (NSN 1615-00-255-2896), (P/N 204-040-366-15) ON ALL UH-1, EXCEPT UH-1C/M, AIRCRAFT. ROUTINE TRACKING OF THE STATUS OF THE CHANGE OUT HAS BEEN THROUGH THE DA FORM 2410 PROGRAM. IN ORDER TO CONFIRM AND/OR UPDATE THE STATUS IN THE TAMMS RECORD, REQUEST AN IMMEDIATE INSPECTION TO DETERMINE IF ANY UH-1 AIRCRAFT ARE STILL EQUIPPED WITH THE THIN WALL MAST, (NSN 1615-00-073-8203), (P/N 204-040-366-9).

1. PRIORITY CLASSIFICATION - FIVE (5) DAYS UPON RECEIPT OF THIS MESSAGE THE CONDITION STATUS OF THE SUBJECT AIRCRAFT WILL BE CHANGED TO A CIRCLE RED //X//. AFTER FIVE (5) DAYS, CONDITION WILL BE CHANGED TO A RED //X//.

3. INSPECTION PROCEDURE -

A. GAIN ACCESS TO DATA PLATE ON MAIN ROTOR MAST AND RECORD PART NUMBER AND SERIAL NUMBER.

PAGE 04 RUCIFRD7083 UNCLAS

B. VERIFY THAT YOUR DA FORM 2408-16 REFLECT THE CORRECT STATUS OF THE CURRENTLY INSTALLED MAST ASSEMBLY. RE-ACCOMPLISH AND RESUBMIT DA FORM 2410 COMPLETING SECTION ONE (I) AND SECTION FOUR (IV) AS PER INSTRUCTION IN TM 38-750 (MAY 81) PER 1D-21, AND ENTER IN THE REMARKS CHECK THE STATEMENT "CORRECTED COPY MAY 84", TO REPORT THE PRESENTLY INSTALLED MAST ASSEMBLIES.

PART NUMBER - 204-040-366-9, FSN 1615-00-073-8203

PART NUMBER - 204-040-366-15, FSN 1615-00-255-2896

C. MAILING ADDRESS FOR B IS, AVSCOM, DRSAV-MPSD, ATTN - MIKE DERMODY, 4300 GOODFELLOW BLVD, ST. LOUIS, MO 63120, BY 14 MAY 1984.

4. RECORDING AND REPORTING OF INSPECTION -

A. RECORD ACCOMPLISHMENT OF YOUR INSPECTION IN ACCORDANCE WITH THE PROCEDURE IN TM 38-750. THE FOLLOWING FORMS ARE APPLICABLE -

(1) DA FORM 2408-13, AIRCRAFT INSPECTION AND MAINTENANCE RECORD.

(2) DA FORM 2408-05 EQUIPMENT MODIFICATION RECORD.  
B. SAFETY OF FLIGHT MESSAGE FOLLOW-UP RCS CBGLD 1860. MACOM'S AND OTHER ACTION ADDRESSEES, UPON COMPLETION OF THE REQUIREMENT SET FORTH IN PARAGRAPH THREE (3) OF THIS MESSAGE, OR NOT LATER THAN 30

BT

80552



MSG 8 TIME RADAY PRIORITY  
38374 0188 117/84  
3208W 940TH 453FTS NAVY AERO COMB DPC DPM CONSEC LGT ACFT ACD OSI NCAX CAP 000C  
DOJ AUDITOR 4CAF ADC JA DOTH 0005 SSF SS  
APP ACE DET T/A FTW/CC ABC/CC MA XPR LOS SE WEA PA W/DO XPNT LCC FCS SG OT

PCTUZEXV RULHEA0553 1170050 0000--RUUMDTA.

FM ARHG OAC APC MD //NSG-AVN-L//  
TO AIG 7401

RUESSKA/TAC VI CHRISTIANSTED ST CROIX VI  
ACCT DA-BHCSVD

FM CDRAVSCOM STL HQ //DRSAV-M//  
TO AIG 8831

RUELRFA/US EVN PROT AGY PO BOX 15027 LAS VEGAS NV  
RUEVDAB/US EVN PROT AGY REGION II 20 FEDERAL PLAZA NY NY  
RUEVLAN/NATIONAL OCEANIC AND ATMOSPHERIC ADM ROCKVILLE MD  
//ROAR/A02 COL L. A. WEAVER//  
RUEVHFP/NASA KENNEDY SPACE CENTER CAPE CANAVERAL FL  
//SI-SAT-23//

RUEHIN/AIT TAIPEI  
RUEHC/AIT WASH DC

RUEHSH/COMUSMILCP SAN SALVADOR EL SALVADOR //SCES-AF//  
RUESSG/COMUSMILCP BOGOTA COLUMBIA //SCCD-AFDC//

RUCDCOH/REDSTONE ARSENAL AL //DRSHI-ST//  
RUEVHAD/US CUSTOMS SERVICE DEPT OF TREASURY

RUCJAAA/CDR US REDCOM MCDILL AFB FL //RCCS-AVN//  
NFO AIG 9004

AIG 7515

RUCLEUA/CDRUSAAVNC FT RUCKER AL //ATZO-DI//  
RUAMAD/USDAO TEL AVIV ISRAEL

PAGE 02 RUCIFRD UNCLAS

RUEHC/SEC STATE WASH DC //HEA/MFO//

RUEHRO/ANEMB ROME ITALY //00C//

RUEOPNA/DISC PHILADELPHIA PA //0ESB-JU//

RUCJAAA/USCINCPAC MCDILL AFB FL //RCCS-AVN//

RUEHBT/CJUBNACTHAI BANGKOK THAILAND

RUFLEFA/CDUSMAQ MAAG MADRID SPAIN //ARMY/NAVY SEC//

RAYRAC/MOSCENG MELBOURNE AUSTRALIA //SOAIR ENG//

RAYWPP/DEPAIR CANTERRA AUSTRALIA //OPHEL-AF//

RUEVDEE/USDA FOREST SERVICE PO BOX 2417 WASH DC 20013

//COOPERATIVE FIRE PROTECTION//

ACCT DA-BHCSVD

BT

UNCLAS

FINAL SECTION OF D2

APRIL 1984. WILL FORWARD A MESSAGE REPORT OF ACTION ACCOMPLISHED TO  
COMMANDER, AVSCOM, ATTN: DRSAV-MPSD, PER AR 95-18. THE REPORT WILL  
CITE THE SAFETY OF FLIGHT MESSAGE, TS NUMBER, THE AIRCRAFT MISSION  
DESIGN SERIES (NDS), AND SERIAL NUMBERS OF THE AIRCRAFT TO INCLUDE  
REQUESTED PART NUMBERS AND SERIAL NUMBERS OF MAJOR ASSEMBLIES.

C. FOR AIRCRAFT IN DEPOT MAINTENANCE AWAITING DISPOSITION OR IN  
STORAGE, TAKE THE FOLLOWING ACTIONS -

AM.  
ARMY



RCV MSG # TIME RAD. ROUTINE  
53524 1512 153/84  
3200NH 940TH 453FTS NAVY AERO COMM DPC DPM CONSEC LGT ACF ACD OSI NCAX CAP DOOC  
DOJ AUDITOR 4CAF ADC JA DOTH DOOS SSF SS  
D ACE DET T/A FTW/CC ASG/CC NA XPR LGS SE YEA PA W/DO XPNT LGC FCS BG OT

ACTUZEKU RULNETC3917 1531329-~~0000~~-RUMMDTA 29

ARMY

~~ZNR 00000~~  
R 011300Z JUN 84 ZEX  
FM CNGB WPG MD //HGB-AVN-LS//  
TO AIG 7401  
RULNETC3917 VI CHRISTIANSTED ST CROIX VI  
AIG 7305  
INFO RUMDEA/CDR AVCRAD CA FRESNO CA  
RUCLRFA/CDR AVCRAD CT BOX I GROTON-NEW LONDON ARPT GROTON CT  
RUCLRFA/CDR AVCRAD MD RT 6 BOX 345 MUNI ARPT SPRINGFIELD MD  
RUCLRFA/CDR AVCRAD MS PO BOX 3349 GULFPORT MS  
RUCIFRD/CDR AVSCON STL MO //DRSAV-WV//  
ACCT DA-BHCSVD

UH-1S4-04  
thin wall  
mast

BT  
UNCLAS  
AVSCON FOR MR. HOLTGREVEN  
SUBJ UH1 MAST ASSY, THIN WALL REPLACEMENT  
A. MSG AVSCON P 252015Z APR 84 SAFETY OF FLIGHT MSG UH-1-84-04.  
B. MSG HGR P 252352Z APR 84 SAB.  
1. REF MSG PLACED RNTS FOR INSPECTION OF UH1 FLEET TO ASCERTAIN  
NUMBER OF ACFT WITH THIN WALL MAST ASSY (NSN 1615-00-073-8203,  
PH 204-040-366-9).

PAGE 02 RULNETC3917 UNCLAS  
2. REPLACEMENT THICK WALL MAST ASSY (NSN 1615-00-255-2896, PH  
204-040-366-15) WILL BE SHIPPED TO EA AVCRAD IN INCREMENTS OF 10  
EA AND WILL BE ISSUED USING AINI PROCEDURES. REQUISITIONS FROM  
USERS WILL BE ROUTINE AND ARE NOT TO GROUND ACFT AS NOT MISSION  
CAPABLE SUPPLY (HMCS). EA USER SHOULD COOR ISSUES W AINI/DX MGR.  
3. REQ AINI/DX MGR REPORT ISSUES BY STATE AND ACFT SERIAL NUMBER  
TO HGB POC ON A WEEKLY BASIS (EACH FRIDAY).  
4. THIN WALL MAST ASSY (NSN 1615-00-073-8203, PH 204-040-366-9)  
REMOVED FROM ACFT WILL BE CONDEMNED IAW TM 55-1500-325-25, PARA 4-5  
A-6.  
5. POC AT HGB-AVN IS MR. BURRIL, AUTOVON 584-4700.  
BT  
53917

14344 0104 133034  
CZDRM 340TH 43378 NAVY BOMB CORP 376 BFM 24400 LST WCF HQD CBI NGRN LAF DDC  
BOX ANDITR 404F KIC 24 DATH D145 BPF 33  
A HCF DET T/O FTYMCC ADDVCC M4 XPE LGS SE MEA FR M/DC NPMT LDC FCS 5G 17

030202XV ROLNE00022 136190T-0000--F0000TA  
RNR 00000  
0171830Z MAY 84 ZEX  
R 0250 000 4PC HQ//NGB-044-L//

ARMY  
WS  
8234  
ND

RIG 7085  
RLE000A/TAG VI ST CRAIX CHRISTIANSTED VI  
R 171830Z MAY 84  
R 000000000 STL HQ //DRSAY-M//  
R 015 6713  
R 01000A/US EWR PROT AGY PO BOX 15027 LAS VEGAS NV  
R 01000A/US EWR PROT AGY REGION 11 20 FEDERAL PLAZA NY NY  
R 01000A/NATIONAL OCEANIC AND ATMOSPHERIC ADM ROCKVILLE MD  
R 00000A/02 COL L. W. MEYER//  
R 01000A/NASA KENNEDY SPACE CENTER CAPE CANAVERAL FL  
R 01-00T-23//  
R 01000A/TRIPLI  
R 01000A/WASH DC

R 01000A/AMSMILIT SAN SALVADOR EL SALVADOR //0000-AF//  
R 01000A/COMUSMILCP BOGOTA COLOMBIA //0000-APDH//  
R 01000A/REDSTONE ARSENAL MS //0000-RT//  
R 01000A/US CUSTOMS SERVICE DEPT OF TREASURY  
R 01000A/US HQ REGION MCILL AFB FL //0000-044//  
R 01 015  
R 01000A/CONUS/USMC FT RUCKER AL //0100-01//  
R 01000A/USDPAA TEL AVIV ISRAEL

R 01000A/STATE WASH DC //0100-01//  
R 01000A/EMBASSY WFOO ROME ITALY //0000//  
R 01000A/DISC PHILADELPHIA PA //0000-JU//  
R 01000A/US HQ REGION MCILL AFB FL //0000-044//  
R 01000A/USMAG BARNOCK THAILAND  
R 01000A/USMAG MADRID SPAIN //0000-044//  
R 01000A/USMAG MELBOURNE AUSTRALIA //0000-044//  
R 01000A/USMAG CANBERRA AUSTRALIA //0000-044//  
R 01000A/USMAG FIRE PROTECTION SERVICE PO BOX 2417 WASH DC  
R 01000A/COOPERATIVE FIRE PROTECTION//  
R 01 015

01000A/EL OF DC  
01000A/INSTALLATION OF THICK WALL POSTS. NSN 1615-00-255-2896.  
R 01 015-040-066-15  
NOTE: THIS IS NOT A SAFETY OF FLIGHT MESSAGE AND HAS NOT. REPEAT.  
IT HAS BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES  
ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL  
SUBORDINATE UNITS. ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED.



PAGE 03 #0C1FR06629 UNCLAS

RETRANSMISSION SHALL REFERENCE THIS MESSAGE. ACTION ADDRESSEES  
SHALL IMMEDIATELY VERIFY THIS RETRANSMISSION TO COMMANDER, AVSCOM,  
ATTN - OPSAV-M.

AVSCOM OPSAV-M 052015Z APR 84 300J SAFETY OF FLIGHT MAINTENANCE  
ROUTARY MESSAGE, ONE TIME INSPECTION OF UH-1 TAMMS DA FORM 2410  
REPORTING SYSTEM CONCERNING UH-1 MOTOR MAST ASSEMBLY VERIFICATION  
(UH-54-04) (U)

SUMMARY - THICK WALL MASTS WERE INTRODUCED INTO THE UH-1 FLEET  
IN 1977 ON AN ATTRITION BASIS. THE PHYSICAL INVENTORY ACCOMPLISHED  
UNDER REFERENCED MESSAGE SHOWS THE OBJECTIVE OF THIS PROGRAM HAS  
NOT BEEN ACCOMPLISHED WITHIN THE TIME FRAME INITIALLY ENVISIONED.  
IN ORDER TO STANDARDIZE FLEET CONFIGURATION AND PROVIDE LOGISTIC  
COMMONALITY, ALL THIN WALL MASTS, NSN 1445-00-073-6200, P/N 204-  
240-344-7, WILL BE CHANGED AT AVON LEVEL ON AN EXPEDITED, SYSTEM-  
ATIC BASIS. THICK WALL MASTS CURRENTLY IN THE INVENTORY WILL BE  
ISSUED TO ACONUS MACONS AND HIGH PRIORITY CONUS UNITS DURING THE  
THIRD AND FOURTH WEEKS OF MAY 84. 40 MASTS FROM NEW PRODUCTION AND  
REPAIR BECOME AVAILABLE, ALL UNITS REQUIRING THICK WALL MASTS WILL  
BE CONTACTED TO SUBMIT REQUISITIONS. MASTS WILL BE REQUISITIONED  
FROM AND SHIPPED TO AUTHORIZED AINI POINTS TO THE EXTENT POSSIBLE.

PAGE 04 #UC1FR06629 UNCLAS

IT IS EXPECTED THAT SUFFICIENT ASSETS WILL BE AVAILABLE BY 30 SEP  
84 TO COMPLETE UH-1H/V CHANGE OUT. PROCEDURES FOR ACCOMPLISHMENT  
OF CHANGE OUT PROGRAM ARE -

A. COMPLIANCE TIME - UNITS ARE AUTHORIZED 48 HOURS PER AIRCRAFT  
TO INSTALL MAST ASSEMBLY AFTER RECEIPT FROM AINI POINTS. THIRTY DAYS  
MAXIMUM TIME AUTHORIZED TO COMPLETE ENTIRE UNIT CHANGE-OUT  
EXAMPLE - INDIVIDUAL UNITS WITH ONE MAST CHANGE WILL BE EXPECTED TO  
COMPLETE INSTALLATION WITHIN 48 HOURS. UNITS HAVING TWO MASTS ARE  
AUTHORIZED FOUR DAYS TO COMPLETE CHANGE-OUT AND SO ON UP TO A  
MAXIMUM OF 30 DAYS. AVSCOM WILL TRACK MAST SHIPMENT AND RECEIPT  
DATES TO AINI POINTS TO PRECLUDE ANY DELAYS IN MAST ISSUES TO  
REQUIRING UNITS.

B. REQUISITIONING PROCEDURES - AS THICK WALL MASTS BECOME  
AVAILABLE, THIS COMMAND WILL ADVISE AINI COORDINATOR TO SUBMIT  
REQUISITION BY MESSAGE TO OPSAVSCOM, ATTN OPSAV-SCONS, NATIONAL  
HEAD AND RESERVES ARE AUTHORIZED A ONE TIME EXCEPTION TO REQUISITION  
OF MAST ASSEMBLY USING MILSTRIP PRIORITY DESIGNATOR 03. THICK WALL  
MASTS WILL BE DISTRIBUTED BY PRIORITY TRANSPORTATION. A SMALL  
QUANTITY OF MASTS WILL BE HELD BY AVSCOM TO FILL NMCS REQUISITIONS.  
EXTRA REQUISITIONS WILL NOT BE USED TO FILL CHANGE OUT

PAGE 05 #UC1FR06629 UNCLAS

REQUIREMENTS. POINTS OF CONTACT ARE MR. GAINES PICKETT, CDR, AVSCOM,  
OPSAV-SAV, AUTOVON 603-3653 OR COMMERCIAL (314) 263-3653 OR MR. BOB  
LAWSON, AUTOVON 493-3506 OR COMMERCIAL (314) 263-3506

00000

UN MSG # TIME RADA PRIORITY  
45345 0105 139/84  
1.05PM 240TH 453FTS NAVY AERO COMM DPC DPH CONSEC LGT WCF ACD OSI NCAX CAP DOOC  
DOJ AUDITOR 4GAF ADC JA DOTM DOOS SSF SS  
D ACE DET T/A FTW/CC ABG/CC NA XPR LGS SE NEA PA W/DO XPNT LCC FCS SG OT

7CTUZEKM RULNEA0323 1381907-UUUU--RUWMDTA  
UUUUU

171630Z MAY 84 ZEX  
FM ORRG SAC APS MD//HQB-AVN-L//

*25 ARMY*  
*SECRET*

TO AIG 7305

RULSKA/TAG VI ST CROIX CHRISTIANSTED VI  
171630Z MAY 84

FM CDRAVSCOM STL MO //DRSAV-M//  
TO AIG 4713

FUCLPFA/US EVN PROT AGY PO BOX 15027 LAS VEGAS NV  
FUCLPFA/US EVN PROT AGY REGION 11 20 FEDERAL PLAZA NY NY  
FUEOLMA/NATIONAL OCEANIC AND ATMOSPHERIC ADM ROCKVILLE MD

W/000A/ACC COL L. A. WEAVER//  
FUCLAVN/NASA KENNEDY SPACE CENTER CAPE CANAVERAL FL

ST-SAT-23//

FUEHC/AIT TAIPEI  
FUEHC/AIT WASH DC

FUEHSH/COMUSMILGP SAN SALVADOR EL SALVADOR //SCES-AF//

FUECBBG/COMUSMILGP BOGOTA COLOMBIA //SCCD-AFDCM//

FUECDBA/REDSTONE ARSENAL AL //DRSMI-ST//

FUEHTR/US CUSTOMS SERVICE DEPT OF TREASURY

FUEJAAA/CDR US REDCOM MCDILL AFB FL //RCCS-AVN//

O AIG 3004

AIG 7515

FUELENG/CDRUSAVMC FT RUCKER AL //ATZQ-DI//

FUEHAB/CDRDAO TEL AVIV ISRAEL

PAGE 02 RUCIFRO UNCLAS

FUEHC/SEC STATE WASH DC //HEA/MFO//

FUEHRO/US EMBASSY (HFO) ROME ITALY //ODC//

FUEOPHA/DISC PHILADELPHIA PA //OEBB-JU//

FUEJAAA/CDR US REDCOM MCDILL AFB FL //RCCS-AVN//

FUEHST/CJUSMAG BANGKOK THAILAND

FUEPLAFA/CJUSMAG MADRID SPAIN //ARMY/NAVY SEC//

FAYAAC/NSCENG MELBOURNE AUSTRALIA //SOAIR ENG//

FAYMPP/DEFAIR CANBERRA AUSTRALIA //OPHEL-AF//

FUEVDFL/USDA FORREST SERVICE PO BOX 2417 WASH DC

COOPERATIVE FIRE PROTECTION//

CCJ DA-BHCSVD

UNCLAS

SECTION OF 02

C. MAINTENANCE PROCEDURES - MAINTENANCE INSTRUCTIONS FOR  
CHANGING OF THESE MASTS WILL BE IN ACCORDANCE WITH TM 55-1020-210-23.

DATED 20 FEB 79, CHG 40, 7 DEC 83.

D. DA FORM 2410 REPORTING PROCEDURES - REFERENCE TM 35-750.

E. TO ASSIST TRACKING, ENTER IN THE REMARKS BLOCK OF DA FORM  
2410, "MAST CHANGE PROGRAM" AND PROVIDE POC, PHONE NUMBERS AUTOVON/



PAGE 03 RUCIFRD6631 UNCLAS  
COMMERCIAL.

2. FORWARD THE HARD COPY OF DA FORM 2410 FOR EACH INDIVIDUAL SECTION TO INCLUDE DISPOSAL TO CDR, AVSCOM, ATTN DRSAV-NPSC (MIKE PERBODY) 4300 GOODFELLOW BLVD., ST. LOUIS, MO 63120 AUTOVON 693-1955 OR COMMERCIAL (314) 263-1955.

E. DISPOSITION INSTRUCTIONS -

1. DD FORM 1357 UNSERVICEABLE (CONDEMNED) TAG/MATERIEL RED WILL BE INITIATED IAW TB 750-126. ENTER MATERIEL CONDITION CODE "H" IN THE CONDITION CODE BLOCK.

2. THIN WALL MAST ASSEMBLIES, P/N 204-040-366-9, TO INCLUDE MAST PLUG DISPLACED BY THICK WALL MASTS ASSEMBLIES WILL BE CONDEMNED IAW TM 55-1500-328-25, PARAGRAPH 4-5A.6.

3. DISPOSITION INSTRUCTIONS FOR ALL THIN WALL MAST ASSEMBLIES INSTALLED/NOT INSTALLED ARE THE SAME.

F. STATUS REPORTING

1. TO MEET DA REPORTING REQUIREMENTS MACOM'S ARE REQUESTED TO UPDATE WEEKLY BY MESSAGE THE STATUS OF -15 INSTALLATION BY UNIT TAIL NUMBER TO CDR AVSCOM, ATTN DRSAV-WU (MR. CHUCK HOLTGREYEN OR MS. NORMA SILL), AUTOVON 693-1248 OR COMMERCIAL (314) 263-1248. THE REPORT WILL INCLUDE INSTALLATIONS COMPLETED THROUGH 25 MAY 84 AND BE

PAGE 04 RUCIFRD6631 UNCLAS

DUE EVERY FRIDAY THEREAFTER. NEGATIVE REPORTS ARE REQUIRED.

2. UPON NOTIFICATION BY AVSCOM OF SHIPMENT OF THICK WALL MAST ASSEMBLIES, AINI COORDINATORS WILL NOTIFY AVSCOM OF RECEIPT OR NON-RECEIPT WITHIN FIVE DAYS. NOTIFY CDR AVSCOM, ATTN DRSAV-SDDXS WITH INFO TO DRSAV-WU.

G. WEIGHT AND BALANCE DATA

1. UH-1D/H WITH MAST PLUG. CHANGE IN BASIC WEIGHT 13.8 POUNDS. CHANGE IN BASIC MOMENT/100 18.73 INCH POUNDS.

2. UH-1D/H WITHOUT MAST PLUG. CHANGE IN BASIC WEIGHT 17.0 POUNDS. CHANGE IN BASIC MOMENT/100 23.00 INCH POUNDS. CORRECT DD 365C (CHART C) USING ABOVE DATA. MWO 55-1500-219-30-9 DATED 31 AUG 78 WITH CHANGES IS RESCINDED BY AUTHORITY OF THIS MESSAGE.

3. MACOM'S ARE ALSO REQUESTED TO PROVIDE POINTS OF CONTACT TO INCLUDE NAMES, ADDRESSES AND PHONE NUMBERS WITHIN FIVE DAYS UPON RECEIPT OF MESSAGE TO CDR AVSCOM, ATTN DRSAV-WU (MR. CHUCK HOLTGREYEN OR MS. NORMA SILL). THIS WILL ENABLE AVSCOM TO EXPEDITE COORDINATION/TRACKING PROCEDURES.

4. POINTS OF CONTACT AT THIS COMMAND ARE LTC DON FOSTER, DRSAV-WU, AUTOVON 693-1248 OR COMMERCIAL (314) 263-1248, OR MR. BOB JOHNSON, DRSAV-SAJ, AUTOVON 693-3506 OR COMMERCIAL (314) 263-3506.

BT

00323



RUEVDEE/USDA FOREST SERVICE PO BOX 2417 WASH DC 20013  
//COOPERATIVE FIRE PROTECTION//  
ACCT DA-BHCSVD  
BT

*UH-1-34 of  
Thin wall  
mast*

UNCLAS  
SECTION 01 OF 02  
SUBJECT - SAFETY OF FLIGHT MAINTENANCE MANDATORY MESSAGE, ONE TIME  
INSPECTION OF UH-1 TAMMS 2410 REPORTING SYSTEM CONCERNING UH-1 ROTOR  
MAST ASSEMBLY VERIFICATION (UH-1-04-04)  
NOTE - THIS IS A SAFETY OF FLIGHT, MAINTENANCE MANDATORY, ONE TIME  
INSPECTION MESSAGE, RELEASED IN ACCORDANCE WITH AR 95-18, DATED 1 MAY  
1980 AND HAS NOT, REPEAT, HAS NOT BEEN TRANSMITTED TO UNITS  
SUBORDINATE TO ADDRESSEES. ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT

252015Z APR 84

PAGE 03 RUCIFRD7083 UNCLAS  
THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS  
AFFECTED OF CONCERNED. THE RETRANSMITTAL SHALL REFERENCE THIS  
MESSAGE. ACTION ADDRESSEES WILL IMMEDIATELY VERIFY THIS  
RETRANSMISSION TO COMMANDER, AVSCOM, ATTN - DRSAV-MPSD.  
SUMMARY - IN 1978 THE ARMY INITIATED, ON AN ATTRITION BASIS, A CHANGE  
OUT OF THE THIN WALL MASTS (NSN 1615-00-073-8203), (P/N  
204-040-366-9) TO THE THICK WALL MASTS (NSN 1615-00-255-2896), (P/N  
204-040-366-15) ON ALL UH-1, EXCEPT UH-1C/M, AIRCRAFT. ROUTINE  
TRACKING OF THE STATUS OF THE CHANGE OUT HAS BEEN THROUGH THE DA FORM  
2410 PROGRAM. IN ORDER TO CONFIRM AND/OR UPDATE THE STATUS IN THE  
TAMMS RECORD, REQUEST AN IMMEDIATE INSPECTION TO DETERMINE IF ANY  
UH-1 AIRCRAFT ARE STILL EQUIPPED WITH THE THIN WALL MAST, (NSN  
1615-00-073-8203), (P/N 204-040-366-9).  
1. PRIORITY CLASSIFICATION - FIVE (5) DAYS UPON RECEIPT OF THIS  
MESSAGE THE CONDITION STATUS OF THE SUBJECT AIRCRAFT WILL BE CHANGED  
TO A CIRCLE RED //X//. AFTER FIVE (5) DAYS, CONDITION WILL BE  
CHANGED TO A RED //X//.  
3. INSPECTION PROCEDURE -  
A. GAIN ACCESS TO DATA PLATE ON MAIN ROTOR MAST AND RECORD PART  
NUMBER AND SERIAL NUMBER.

PAGE 04 RUCIFRD7083 UNCLAS  
B. VERIFY THAT YOUR DA FORM 2408-16 REFLECT THE CORRECT STATUS  
OF THE CURRENTLY INSTALLED MAST ASSEMBLY. RE-ACCOMPLISH AND RESUBMIT  
DA FORM 2410 COMPLETING SECTION ONE (I) AND SECTION FOUR (IV) AS PER  
INSTRUCTION IN TM 38-750 (MAY 81) PER 10-21, AND ENTER IN THE REMARKS  
BLOCK THE STATEMENT " CORRECTED COPY MAY 84 ", TO REPORT THE  
PRESENTLY INSTALLED MAST ASSEMBLIES.  
PART NUMBER - 204-040-366-9, FSN 1615-00-073-8203  
PART NUMBER - 204-040-366-15, FSN 1615-00-255-2896  
C. MAILING ADDRESS FOR B IS, AVSCOM, DRSAV-MPSD, ATTN - MIKE  
DERMODY, 4300 GOODFELLOW BLVD, ST. LOUIS, MO 63120, BY 14 MAY 1984.  
4. RECORDING AND REPORTING OF INSPECTION -  
A. RECORD ACCOMPLISHMENT OF YOUR INSPECTION IN ACCORDANCE WITH  
THE PROCEDURE IN TM 38-750. THE FOLLOWING FORMS ARE APPLICABLE -  
(1) DA FORM 2408-13, AIRCRAFT INSPECTION AND MAINTENANCE  
RECORD.  
(2) DA FORM 2408-05 EQUIPMENT MODIFICATION RECORD.  
B. SAFETY OF FLIGHT MESSAGE FOLLOW-UP RGS CSGLD 1060. MACOM'S  
AND OTHER ACTION ADDRESSEES, UPON COMPLETION OF THE REQUIREMENT SET  
FORTH IN PARAGRAPH THREE (3) OF THIS MESSAGE, OR NOT LATER THAN 30  
BT  
#7083

NNNN  
4755210EVDFL

Time: 01:22 04/26/84 GMT  
Connect Time: 169 seconds

WILL IMMEDIATELY VERIFY THIS RETRANSMISSION TO COMMANDER, AVSCOM,  
ATTN - DRSAV-WU.

A. AVSCOM DRSAV-M 252015Z APR 84 SUBJ SAFETY OF FLIGHT MAINTENANCE  
MANDATORY MESSAGE, ONE TIME INSPECTION OF UH-1 TAMMS DA FORM 2410  
REPORTING SYSTEM CONCERNING UH-1 ROTOR MAST ASSEMBLY VERIFICATION  
(A-84-04) (U)

1. SUMMARY - THICK WALL MASTS WERE INTRODUCED INTO THE UH-1 FLEET  
IN 1977 ON AN ATTRITION BASIS. THE PHYSICAL INVENTORY ACCOMPLISHED  
UNDER REFERENCED MESSAGE SHOWS THE OBJECTIVE OF THIS PROGRAM HAS  
NOT BEEN ACCOMPLISHED WITHIN THE TIME FRAME INITIALLY ENVISIONED.  
IN ORDER TO STANDARDIZE FLEET CONFIGURATION AND PROVIDE LOGISTIC  
COMMONALITY, ALL THIN WALL MASTS, NSN 1615-00-073-8203, P/N 204-  
040-366-9, WILL BE CHANGED AT AVUM LEVEL ON AN EXPEDITED, SYSTEM-  
ATIC BASIS. THICK WALL MASTS CURRENTLY IN THE INVENTORY WILL BE  
ISSUED TO OCONUS MACOMS AND HIGH PRIORITY CONUS UNITS DURING THE  
THIRD AND FOURTH WEEKS OF MAY 84. AS MASTS FROM NEW PRODUCTION AND  
REPAIR BECOME AVAILABLE, ALL UNITS REQUIRING THICK WALL MASTS WILL  
BE CONTACTED TO SUBMIT REQUISITIONS. MASTS WILL BE REQUISITIONED  
FROM AND SHIPPED TO AUTHORIZED AIMI POINTS TO THE EXTENT POSSIBLE.

PAGE 04 RUCIFRD6629 UNCLAS

IT IS EXPECTED THAT SUFFICIENT ASSETS WILL BE AVAILABLE BY 30 SEP  
84 TO COMPLETE UH-1H/V CHANGE OUT. PROCEDURES FOR ACCOMPLISHMENT  
OF CHANGE OUT PROGRAM ARE -

A. COMPLIANCE TIME - UNITS ARE AUTHORIZED 48 HOURS PER AIRCRAFT  
TO INSTALL MAST ASSEMBLY AFTER RECEIPT FROM AIMI POINTS. THIRTY DAYS  
IS MAXIMUM TIME AUTHORIZED TO COMPLETE ENTIRE UNIT CHANGE-OUT.  
EXAMPLE - INDIVIDUAL UNITS WITH ONE MAST CHANGE WILL BE EXPECTED TO  
COMPLETE INSTALLATION WITHIN 48 HOURS. UNITS HAVING TWO MASTS ARE  
AUTHORIZED FOUR DAYS TO COMPLETE CHANGE-OUT AND SO ON UP TO A  
MAXIMUM OF 30 DAYS. AVSCOM WILL TRACK MAST SHIPMENT AND RECEIPT  
DATES TO AIMI POINTS TO PRECLUDE ANY DELAYS IN MAST ISSUES TO  
REQUIRING UNITS.

B. REQUISITIONING PROCEDURES - AS THICK WALL MASTS BECOME  
AVAILABLE, THIS COMMAND WILL ADVISE AIMI COORDINATOR TO SUBMIT  
REQUISITION BY MESSAGE TO CDRAVSCOM, ATTN DRSAV-SDDXS. NATIONAL  
GUARD AND RESERVES ARE AUTHORIZED A ONE TIME EXCEPTION TO REQUISITION  
-15 MAST ASSEMBLY USING MILSTRIP PRIORITY DESIGNATOR 03. THICK WALL  
MASTS WILL BE DISTRIBUTED BY PRIORITY TRANSPORTATION. A SMALL  
QUANTITY OF MASTS WILL BE HELD BY AVSCOM TO FILL NMCS REQUISITIONS.  
NMCS REQUISITIONS WILL NOT REPEAT WILL NOT BE USED TO FILL CHANGE OUT

PAGE 05 RUCIFRD6629 UNCLAS

REQUIREMENTS. POINTS OF CONTACT ARE MR. GAINES PICKETT, CDR, AVSCOM,  
DRSAV-SAJ, AUTOVON 693-3653 OR COMMERCIAL (314) 263-3653 OR MR. BOB  
JOHNSON, AUTOVON 693-3506 OR COMMERCIAL (314) 263-3506.

BT  
#6629



2. FORWARD THE HARD COPY OF DA FORM 2410 FOR EACH INDIVIDUAL ACTION TO INCLUDE DISPOSAL TO CDR, AVSCOM, ATTN DRSV-MPSD (MR. MIKE DERMODY) 4300 GOODFELLOW BLVD., ST. LOUIS, MO 63120. AUTOVON 693-1955 OR COMMERCIAL (314) 263-1955.

E. DISPOSITION INSTRUCTIONS -

1. DD FORM 1557 UNSERVICEABLE (CONDEMNED) TAG/MATERIEL RED WILL BE INITIATED IAW TB 750-126. ENTER MATERIEL CONDITION CODE "H" IN THE CONDITION CODE BLOCK.

2. THIN WALL MAST ASSEMBLIES, P/N 204-040-366-9, TO INCLUDE MAST PLUG DISPLACED BY THICK WALL MASTS ASSEMBLIES WILL BE CONDEMNED IAW TM 55-1500-328-25, PARAGRAPH 4-5A.6.

3. DISPOSITION INSTRUCTIONS FOR ALL THIN WALL MAST ASSEMBLIES INSTALLED/NOT INSTALLED ARE THE SAME.

F. STATUS REPORTING

1. TO MEET DA REPORTING REQUIREMENTS MACOM'S ARE REQUESTED TO UPDATE WEEKLY BY MESSAGE THE STATUS OF -15 INSTALLATION BY UNIT TAIL NUMBER TO CDR AVSCOM, ATTN DRSV-WU (MR. CHUCK HOLTGREVEN OR MS. NORMA SILL), AUTOVON 693-1248 OR COMMERCIAL (314) 263-1248. THE REPORT WILL INCLUDE INSTALLATIONS COMPLETED THROUGH 25 MAY 84 AND BE

PAGE 04 RUCIFRD6631 UNCLAS  
DUE EVERY FRIDAY THEREAFTER. NEGATIVE REPORTS ARE REQUIRED.

2. UPON NOTIFICATION BY AVSCOM OF SHIPMENT OF THICK WALL MAST ASSEMBLIES, AIMI COORDINATORS WILL NOTIFY AVSCOM OF RECEIPT OR NON-RECEIPT WITHIN FIVE DAYS. NOTIFY CDR AVSCOM, ATTN DRSV-SDDXS WITH INFO TO DRSV-WU.

G. WEIGHT AND BALANCE DATA

1. UH-1D/H WITH MAST PLUG. CHANGE IN BASIC WEIGHT 13.8 POUNDS. CHANGE IN BASIC MOMENT/100 18.73 INCH POUNDS.  
2. UH-1D/H WITHOUT MAST PLUG. CHANGE IN BASIC WEIGHT 17.0 POUNDS. CHANGE IN BASIC MOMENT/100 23.00 INCH POUNDS. CORRECT DD 365C (CHART C) USING ABOVE DATA. MWD 55-1500-219-30-9 DATED 31 AUG 78 WITH CHANGES IS RESCINDED BY AUTHORITY OF THIS MESSAGE.

2. MACOMS ARE ALSO REQUESTED TO PROVIDE POINTS OF CONTACT TO INCLUDE NAMES, ADDRESSES AND PHONE NUMBERS WITHIN FIVE DAYS UPON RECEIPT OF MESSAGE TO CDR AVSCOM, ATTN DRSV-WU (MR. CHUCK HOLTGREVEN OR MS NORMA SILL). THIS WILL ENABLE AVSCOM TO EXPEDITE COORDINATION/TRACKING PROCEDURES.

3. POINTS OF CONTACT AT THIS COMMAND ARE LTC DON FOSTER, DRSV-WU, AUTOVON 693-1248 OR COMMERCIAL (314) 263-1248, OR MR. BOB JOHNSON, DRSV-SAJ, AUTOVON 693-3506 OR COMMERCIAL (314) 263-3506.

BT

#6631

PAGE 03 RUCIFRDL537 UNCLAS

DRSAV-MPSD, PER AR 95-18 UNITS WILL BE REPORTED AS DELINQUENT SEVEN DAYS AFTER TRANSMISSION OF THIS MESSAGE. THE REPORT WILL CITE THE SAFETY OF FLIGHT MESSAGE, TB 55-1520-242-20-B, THE AIRCRAFT MISSION DESIGN, SERIES, AND SERIAL NUMBER OF THE AIRCRAFT. IF ALL REQUIRED ACTIONS ARE NOT COMPLETED, THE REPORT WILL ALSO CONTAIN THE DATE BY WHICH IT IS ESTIMATED THEY WILL BE COMPLETED. WHEN THE ESTIMATED DATE OF COMPLETION ARRIVES, THE SERIAL NUMBERS REPORTED PREVIOUSLY AS NOT COMPLIED WITH WILL BE REPORTED BY MESSAGE, WITH PRESENT STATUS AND REVISED ESTIMATED COMPLETION DATE. REVISED ESTIMATED COMPLETION DATES AND STATUS REPORTS WILL CONTINUE TO BE SUBMITTED UNTIL ALL REQUIRED ACTIONS HAVE BEEN COMPLETED AND REPORTED. FOR AIRCRAFT IN DEPOT MAINTENANCE, AWAITING DISPOSITION OR IN STORAGE, TAKE THE FOLLOWING ACTIONS -

(1) IMMEDIATELY UPDATE THE AIRCRAFT LOGBOOK BY ENTERING REQUIREMENTS FOR ACCOMPLISHMENT OF THIS MESSAGE ON THE DA FORM 2408-13.

(2) REPORT BY RETURN MESSAGE BY AIRCRAFT HDE AND SERIAL NUMBER THAT THE AIRCRAFT LOGBOOK HAS BEEN UPDATED TO INCLUDE THIS MESSAGE REQUIREMENT.

(3) PROVIDE A POINT OF CONTACT WITH TELEPHONE NUMBER ON ALL

PAGE 04 RUCIFRDL537 UNCLAS

REPORTS.

ADDITIONAL REPORTING -

A. ALL MAST CHANGED OUTS WILL REQUIRE STANDARD DA FORM 2410 REPORTING FOR REMOVED AND INSTALLED MAST. COMPLETED DA FORM 2410'S ARE TO BE FORWARDED TO AVSCOM, DRSAV-MPSD.

B. ALL NACO'S WILL REPORT TWICE WEEKLY, 1200 HOURS MONDAY AND 1200 HOURS THURSDAY, UNTIL THE THICK WALL MASTS ARE INSTALLED TO DRSAV-MU, LT. COL D. FOSTER, AUTOVON 693-1246 OR COMMERCIAL 314-263-1246. THE FOLLOWING INFORMATION BY TAIL NUMBER -

1. AIRCRAFT DOWN.

2. NUMBER OF MASTS ON HAND TO BE INSTALLED

10. POINT OF CONTACT FOR QUESTIONS CONCERNING FORMS OR REPORTING IS MR. J. RODRIGUEZ, DRSAV-MPSD, AUTOVON 693-1955 OR COMMERCIAL 314-263-1955.

11. FOREIGN MILITARY SALES/F/S RECIPIENTS REQUIRING CLARIFICATION OF THIS MESSAGE SHOULD CONTACT USMRYSCOM, DRSAV-I, CW4 KYLE STEPHENSON, AUTOVON 693-2613 OR COMMERCIAL 314-263-2613.

12. AVSCOM TECHNICAL POINT OF CONTACT IS KEN LUBER, DRSAV-EI, AUTOVON 693-1663 OR COMMERCIAL 314-263-1663.

BT

#0289