

Contents

1. Subject
2. Priority Classification
3. Task/Inspection Suspense Date
4. Reporting Compliance Suspense Date
5. Summary of Problem
6. End Items To Be Inspected
7. Assembly Components to be Inspected
8. Parts to be Inspected
9. Inspection Procedures
10. Correction Procedures
11. Supply/Parts and Disposition
12. Special Tools and Fixtures Required
13. Application
14. References
15. Recording and Reporting Requirements
16. Weight and Balance
17. Points of Contact

*UH-1-94-ASAM-04
modification
to left cyclic rigid
link*

Display Without Table Of Contents

SYNOPSIS UH-1-94-ASAM-04 AVIATION SAFETY ACTION MESSAGE, MAINTENANCE MANDATORY, ALL UH1H/V AIRCRAFT, CLARIFICATION OF UH-1-94-ASAM-03 CONCERNING MODIFICATION TO LEFT CYCLIC RIGID CONNCTING LINK, (TB 1-1520-210-20-23). 221820Z MAR 94, BRAD MEYER, AMSAT-C-XS, X2085. : FROM :CDRATCOM ST LOUIS MO//AMSAT-C-XS// TO :AIG 6713 :AIG 9004 :AIG 9042 :AIG 8708 :AIG 7515 :DCM APMO OZARK AL//DCMDS-RCQA// :ASF42 81ST ARCOM DOBBINS AFB GA :CDR4THBN228THAVN SOTO CANO HO//AVN-AMO// :102DARMY SCOTT AFB IL//AFRC-AMO-ASF-IL// :AMEMBASSY ROME IT//ODC/PASS TO HQ MFO// :DIRAAOD HOLLOMAN AFB NM//STEW-AA/GE GS// :CDRAMCCOM PICATINNY ARSENAL NJ//AMSMC-AV-D// :JOHNSON CONWORLDSVCINC KWAJALEIN NQ//PAR2// :USCS CNAC OKLAHOMA CITY OK//AM// :FORCE COMMANDER SINAI MFO HQ IL TELEX 606342535 : //PASS TO SSO AVSM/SO AIR// :USDOCO LANDSOUTHEAST IZMIR TU//AV// :DPRO BELL HELICOPTER FORT WORTH TX//DCMDS-RBQ/RBDF// :CDROSAC FT BELVOIR VA//ANAV-OS/ANAV-RW-M/ANAV-CR// :WALLOPS FLIGHT FACILITY NASA WALLOPS ISLAND VA : //CODE 831.2 AIRCRAFT QA// INFO :CDRUSASDC WASHINGTON DC//CSSD-ZA// :SEC STATE WASHINGTON DC//NEA/MFO// :US CUSTOMS SERVICE WASHINGTON DC//AVIATION : OPERATIONS// :AFSOC HURLBURT FIELD FL//LGMW// :NAVAIRSYSCOM DET PMA PENSACOLA FL//PMA225// :NAVAVNDEPOT PENSACOLA FL//310B// :WR-ALC ROBINS AFB GA//LUHA// :HQ AMC SCOTT AFB IL//LG/LGA/LGQ/SEF/XO/XOT/XOV/XOX// :CDR FT BRAGG NC//AFZA-GT-OM// :CDR HQ 1ST COSCOM FT BRAGG NC//LOGOPS AVN SECT : AFVH-DC-L// :CDR WHITE SANDS MISSILE RANGE NM//STEW-AA// :DISC PHILADELPHIA PA//QEBB-JU// :CDR LSE AVIATION IZMIR TU//LSE// :HQ ACC LANGLEY AFB VA//DOH/LGRC// :PMSW VHFS WARRENTON VA//SFAE-IW-SG// XMT :USDAO DHAKA BG :USDAO RANGOON BM :USDAO COLOMBO CE :USDAO SUVA FJ :DSA NEW DELHI IN :USDAO ROME IT :USDAO ANTANANARIVO MA :CDRATCOM ST LOUIS MO//AMSAT-C-XS// :SAO KUALA LUMPUR MY :USDAO KATHMANDU NP//SAO// ACCT : TEXT

Subject

AVIATION SAFETY ACTION MESSAGE, MAINTENANCE

MANDATORY, RCS CSGLD-1860(R1), ALL UH-1H/V AIRCRAFT,
CLARIFICATION OF UH-1-94-ASAM-03 CONCERNING MODIFICATION TO
LEFT CYCLIC RIGID CONNECTING LINK (UH-1-94-ASAM-04) (TB 1-
1520-210-20-23)

NOTE - THIS IS AN AVIATION SAFETY ACTION MESSAGE ISSUED PER
AR 95-3, CHAPTER 5 REVISION VIA MESSAGE HQ AVSCOM, AMSAV-
XSOP, 181900Z SEP 90, SUBJECT: CHANGE TO AR 95-3, CHAPTER
5, SAFETY OF FLIGHT MESSAGES. THIS MESSAGE HAS NOT BEEN
TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES. ADDRESSEES
SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL
SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR
CONCERNED. THE RETRANSMITTAL SHALL REFERENCE THE MESSAGE.
ACTION ADDRESSES WILL IMMEDIATELY VERIFY THIS
RETRANSMISSION TO COMMANDER, ATCOM, ATTN - AMSAT-C-XS (SOP
COMPLIANCE OFFICER).

Priority Classification

- NO CHANGE FROM UH-1-94-ASAM-

03.

Task/Inspection Suspense Date

- NO CHANGE FROM UH-1-94-

ASAM-03.

Reporting Compliance Suspense Date

- REPORT IAW UH-1-94-

ASAM-03. NO REPORTING REQUIRED FOR THIS MESSAGE.

Summary of Problem

A. UH-1-94-ASAM-03, DTG 022000Z MAR 94 REQUIRES
MODIFICATION TO SERVO ASSEMBLIES, P/N 205-076-056, EARLY
PRODUCTION UNITS OF THESE ASSEMBLIES DO NOT HAVE P/N 205-076-
056 ON THE DATA PLATE. THESE ASSEMBLIES HAVE A SUBASSEMBLY
PART NUMBER OF P/N 205-076-055 ON THE DATA PLATE. SERVO
ASSEMBLIES WITH SUBASSEMBLY PART NUMBER OF 205-076-055 ON
THE DATA PLATE ARE ALSO REQUIRED TO BE MODIFIED IAW UH-1-94-
ASAM-03.

B. INSERT THE FOLLOWING NOTE PRIOR TO PARA 8B OF UH-1-
94-ASAM-03. ALL OTHER REQUIREMENTS OF UH-1-94-ASAM-03
REMAIN THE SAME.

NOTE

SERVO ASSEMBLIES WITH SUBASSEMBLY PART NUMBER
OF 205-076-055 ON THE DATA PLATE ARE REQUIRED TO BE
MODIFIED PER THIS MESSAGE.

C. THE PURPOSE OF THIS MESSAGE IS TO INFORM UNITS THAT
SERVO ASSEMBLIES WITH P/N 205-076-055 ON THE DATA PLATE ARE
ALSO REQUIRED TO BE MODIFIED IAW UH-1-94-ASAM-03.

5. END ITEMS AFFECTED - ALL UH-1H/V AIRCRAFT.

Assembly Components to be Inspected

- NO CHANGE FROM UH-