

MIL-C-6794  
Coating compound  
GEN-76-07  
reinds  
GEN-76-1

13 FEB 76 14 39z

ARMY  
48

RA TUZEXW RULNEAA0895 0441340-UUUU--RUWMDTA;  
ZNR UUUUU  
R 131327Z FEB 76 ZBX  
FM ARNG OPERATING ACTIVITY CENTER (OAC-AVN-L)  
TO AIG 7401  
INFO RUEFHQA/ONGB WASH DC//NGB-ARL-A//

BT  
UNCLAS  
THE FOLLOWING MESSAGE IS A RETRANSMITTAL FROM CDR AVSCOM STL MD  
//DRSAV-FBQ// DTG 121335 FEB 76, NOTE CLN THIS MESSAGE HAS NOT, REPEAT, HAS NOT  
BEEN TRANSMITTED TO

UNITS SUBORDINATE TO ADDRESSEES, ADDRESSEES ARE RESPONSIBLE  
FOR DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS,  
ACTIVITIES, ELEMENTS, OR FOREIGN USERS AFFECTED OR CONCER-  
NED. RETRANSMITTAL SHALL REFERENCE THIS MESSAGE

SUBJ CLN MAINTENANCE ADVISORY MESSAGE ON COATING COMPOUND (GEN 76-07)

- A, AVSCOM MSG, 141935Z JAN 76 (GEN 76-1)
- B, USAGMPA MSG 231730Z JAN 76, SUBJECT AS ABOVE;
- 1. ACCORDING TO GSA, REFERENCED COATING COMPOUND (MIL-C-6794)
- H BEEN RETESTED AND IS NOT, REPEAT NOT, DEFECTIVE, MATERIAL

PAGE TWO RULNEAA0895 UNCLAS  
SHOULD BE RE-ENTERED INTO SUPPLY SYSTEM;  
2. THEREFORE, AVSCOM MSG 141935Z JAN 76 (GEN 76-1) IS RESCINDED;  
3. POINT OF CONTACT CLN MR. JOHN O. TRESSLER, DIR ORDER PROCESSING  
& CONTROL BRANCH, GSA, FSS, PFC, WASH DC. IN REPLY, REFER TO  
FF001, AC 703-557-1707.

BT  
0895