

*Ni-cad battery cells  
Gen-75-33*

*ARMY/41*

RTTEZEXH RUEDAOA2784 3292131-EEEE--RUMMDTA;  
ZNY EEEEE  
R 252112Z NOV 75  
FM ARNG DAC EDGEWOOD MD //DAC-AVN-L//  
TO AIG 7421  
INFO ONGB WASH DC //ONGB-ARL-A//  
BT  
UNCLAS E F T O  
R 211639Z NOV 75  
FM CDRAVSOCOM STL MO //AMSAV-FEB//  
TO AIG 8881  
INFO AIG 9284  
BT

UNCLAS E F T O  
NOTE OLN THIS MESSAGE HAS NOT, REPEAT HAS NOT BEEN TRANSMITTED TO  
UNITS SUBORDINATE TO ADDRESSEES, ADDRESSEES ARE RESPONSIBLE FOR  
DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES, OR  
ELEMENTS AFFECTED OR CONCERNED; RETRANSMITTAL SHALL REFERENCE THIS  
MESSAGE.

SUBJ OLN MAINTENANCE ADVISORY MESSAGE ON AIRCRAFT NICKEL-CADMIUM  
CELLS, BB-6887A, MANUFACTURED UNDER CONTRACT DAAB25-75-C-

1. (GEN-75-33)  
1. RECENT FIELD INFORMATION INDICATES THE FOLLOWING OLN

26 NOV 75 18 58 Z

PAGE2 RUEDAOA2784 UNCLAS E F T O  
A. CELLS UNDER SUBJECT CONTRACT IDENTIFIED BY MANUFACTURER  
AS BEING SAFT AMERICA, INC, WITH CODE DATE 7/73 AND LATER,  
B. CELL CAPACITY MARKED AS 33AH ON CELL LABEL,  
2. CELL CAPACITY MARKING OF 33AH WAS DUE TO INADVERTENT MARKING  
INSTRUCTION ERROR; CELL CAPACITY IS ACTUALLY 34AH;  
3. THIS MESSAGE AUTHORIZES ALL FACILITIES PERFORMING NICKEL-  
CADMIUM BATTERY MAINTENANCE IN AIRCRAFT APPLICATIONS TO INTERMIX  
GULTON IND., INC., AND SAFT AMERICA, INC., CELLS BEARING THE SAME  
NSN WITHIN THE SAME CASE;  
4. THIS MESSAGE IS BEING DISTRIBUTED AT THE REQUEST OF CDR  
USAECOM, FT MONMOUTH, NJ, AMSL-MA-DM; ANY QUESTIONS REGARDING  
THIS MESSAGE SHOULD BE DIRECTED TO MR. ARTHUR FRINK OF THAT  
ADDRESS, AUTOVON 992-1381/1315;  
BT  
#2784