

3 SEP 75 11 32

ARM

~~RTTUZEXX RUEDA08454 2461372-0000--RUMMDTA~~

ZNR 00000
R 031234Z SEP 75 ZEX
FM CDR ARNG-040 EDGEWOOD MD //040-AVN-L//
TO AIG 7421

ARMY
20

INFO RUSAUSA/NGB WASH DC //NGB-ARL-A//
P R 292229Z AUG 75

UH-1-75-12
stab bar tubes

FM CDRAVS00M STL MO //AMSAV-FGU//
TO AIG 8981

AIG 9242
AIG 7432

INFO AIG 9284
CDR USABPA FT WORTH TX //SAVRE-E//
BT

UNCLAS
NOTE - THIS IS A MAINTENANCE ADVISORY MESSAGE AND HAS NOT,
REPEAT HAS NOT, BEEN TRANSMITTED TO UNITS SUBORDINATE TO
ADDRESSEES; ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS
MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS
AFFECTED OR CONCERNED, THE RETRANSMITTAL SHALL REFERENCE
THIS MESSAGE;
SUBJECT - STABILIZER BAR TUBES USED ON UH-1B/D/H HELICOPTERS

PAGE 2 RUEDA08454 UNCLAS
(UH-1-75-12);

1. STABILIZER BAR TUBES USED ON UH-1B/D/H ARE ASSIGNED A FIVE YEAR CALENDAR LIFE, THIS FIVE YEAR LIFE BEGINS FEBRUARY 1973; TUBES INSTALLED ON HELICOPTERS ON OR BEFORE FEBRUARY 1973 MUST BE REPLACED WITH NEW TUBES BEFORE FEBRUARY 1978, TM 55-1528-219-22, PAGE 3-44 (CHANGE 3, 5 APRIL 1974) CONTAINS THIS INFORMATION;
 2. INFORMATION CONTAINED IN THIS MESSAGE SHOULD BE INSERTED IN TM 55-1528-219-22 OVERHAUL AND RETIREMENT SCHEDULE PENDING RECEIPT OF FORMAL MANUAL CHANGE;
 3. THIS MESSAGE SUPERSEDES PARAGRAPH 6 OF AVS00M MESSAGE 131752Z AUGUST 1973 SUBJECT UH-1 SHRIER HELICOPTER STABILIZER BAR ASSEMBLIES;
- BT
#2454

RTTUZEXW RUEDAQAZ638 2551400-UUUU--RUWMDTA;
NR UUUUU

R 121618Z SEP 75 ZEX

FM ARNG-OAC EDGEWOOD MD //OAC-AVN-L//

TO AIG 7401

NFC RUEFHQA/CNGB WASH DC //NGB-ARL-A//

Army/4/

BT

UNCLAS

SUBJ CLN STABILIZER BAR TUBES USED ON UH-1B/D/H HEL

A, MSG, AMSAV-FEU, USAAVSCOM, 292029Z AUG 75 (UH-1-75-12);

RETRANSMITTED BY OAC-AVN-L, 231234Z SEP 75;

B, MSG, USAAVSCOM, 131752Z AUG 73;

C, MSG, NGB-ARL, CNGB, 301943Z AUG 73;

1, REF B WAS PARAPHRASED AND TRANSMITTED AS REF C;

2, REF C, PARA 7, IS SUPSD,

BT

#0535

NNNN