

UH-1-79-8
T53 eng TBO
on condition

RCTUZYUM RULNNAC1516 1590019-UUUU--RUKMDTA,
ZNR UUUUU
R 080019Z JUN 79
FM HQR ARNG-CAO EDGEWOOD MD//NGB-AVL-L//
TO AIG 7481 - Army
R 071343Z JUN 79
FM CDRUSATSARCOM STL MO//DRSTS-MEP(2)//
TO AIG 8881
AIG 7514
INFO AIG 9804
AIG 7515
RUKTAF/CDR USAABPA FT WORTH TX//DAVBE//DAVBE-C//
RUCLEUA/CDR USAAVNC FT RUCKER ALL//ATZQ-DI//

BT
UNCLAS
NOTE CLN THIS IS A MAINTENANCE INFORMATION MESSAGE AND HAS NOT, REPEAT NOT, BEEN TRANSMITTED TO UNITS SUBORDINATE ADDRESSES, ADDRESSES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED, THE RETRANSMITTAL SHALL REFERENCE THIS MESSAGE.
SUBJECT CLN MAINTENANCE INFORMATION MESSAGE NO. UH-1-79-8 AND AH-1-79-6 FOR UH-1H/H, BH-1H AND AH-1G, TH-1GAIRCRAFT.
PURPOSE OF MESSAGE CLN THE TIME CHANGE COMPONENT COMMITTEE HAS APPROVED THE ELIMINATION OF THE T53-L-13B ENGINE, NSN 2840-00-134-4803 1800 HOUR TIME BETWEEN OVERHAUL (TBO), THIS MESSAGE AUTHORIZES USERS TO CONTINUE THE T53-L-13B ENGINE IN SERVICE AS AN "ON CONDITION"

PAGE 2 RUKTFFC2099 UNCLAS
ITEM,
2. THE T53-L-13B ENGINE AND 1800 HOUR REFERENCE SHALL BE DELETED FROM THE FOLLOWING MAINTENANCE MANUALS CLN
A. TM 55-2840-229-24 DTD 23 APR 71, CHG 5 DTD 15 DEC 78, CHAPTER 13, PAGE 13-1.
B. TM 55-1520-210-23-1 DTD 20 FEB 79, CHAPTER 1, PAGE 1-96, TABLE 1-8.
C. TM 55-1520-220-20 DTD 30 APR 73, CHG 23 DTD 16 AUG 78, CHAPTER 3, PAGE 3-63, TABLE 3-1.
D. TM 55-1520-221-20 DTD 31 DEC 75, CHG 11 DTD 8 SEP 78, CHAPTER 3, PAGE 3-30.
INFORMATION CONTAINED IN THIS MESSAGE SHOULD BE INSERTED IN REFERENCED TH'S PENDING RECEIPT OF THE TAG RPINTED CHANGE.
3. FOREIGN MILITARY SALES (FMS) INTERNATIONAL LOGISTICS (IL) RECIPIENTS SHOULD CONTACT CWO R, BROOK WATKINS, TSARCOM, DRSTS-10(2), A/V 693-8286, COMMERCIAL A/C 314-263-8286 FOR CLARIFICATION OF THIS MESSAGE.
POC FOR THIS ACTION IS FRANK STEVENS, TSARCOM, A/V 693-8396, COMMERCIAL A/C 314-263-8396.