

T53 Engines...

Make a Suitable Wrench



T53 ENGINE MECHANICS OUGHT TO GIVE A LOOK SEE!

Dear Windy,


Page 5-32.1 of the T53 engine repair manual, TM 55-2840-229-23-2, says when replacing the inner drive seal spacer on the starter generator drive seal, to use a suitable wrench. The problem is, there is no suitable wrench in our tool boxes! Sockets and crowsfeet don't really fit and they break.

So I made a tool out of 1/4-in flat steel stock.

Now the job gets done and no tools are broken.

SGT Craig S. Downey
FLARNG

Here's the tool:



Dear Sergeant Downey,

You've solved a problem and saved money, too. What more could you ask for! Good job, Craig.

Windy