




A lot of Huey pitch change link universal bearings bite the dust at overhaul just because they're not completely lubed with the grease gun during PM Periodics.

One side of the bearing winds up smooth as silk—the other side rough as a cob.

'Course, it's easy to reach the lower grease fitting with your needle nose adapter . . . not so with the upper grease fitting.

So you're not 7 feet tall with the reach of a gorilla! Go up there, anyway, using a maintenance stand if necessary.



Purge-lube both fittings until you see the old grease coming out of the bearing, and wipe off the excess. Then, a lot of expensive bearings won't have to be replaced.