


TIME SAVER

MWO's pay big dividends—like the improved grip retention nuts on the Huey 540 main rotor hub. If your Charlie model didn't get 'em, via MWO 55-1520-211-30/18 (15 Jul 66), you're missing a good bet.

The mod, together with MWO 55-1520-211-30/23, Ch 2 (9 Feb 67) gives you an increase in the hub special inspection time from 200 to 600 hrs.



OH-23G HEEBIE-JEBIES...