



If brush cover, P/N 30010-1035, is bolted together with the opening at the top of the generator, slip the cover 180 degrees so that it's at the bottom. Then water won't leak into the generator and short out the works.