

Sliding window

19 372

21

BTUZDSW RULNETC2156 0601649-UUUU--RUKMDTA;
VR UUUUU CORR COPY RULNETC2156
271721Z FEB 80 ZEX
M ARNG-OAC EDGEWOOD AREA APG MD//NGB-AVN-L//
O AIG 7401
JLGSAA/TAG VI ST CROIX VI
261700Z FEB 80
M CDRTSARCOM STL MO//DRSTS-SAJB//
O AIG 8881

CORRECT COPY

None yet ARMY

UNCLAS
SUBJECT - DEFECTIVE UH-1 WINDOW PANELS; NSN 1560-00-690-7290
NOTE - THIS MESSAGE HAS NOT, REPEAT NOT, BEEN RETRANSMITTED TO
UNITS SUBORDINATE TO ADDRESSEES. ADDRESSEES SHOULD IMMEDIATELY RE-
TRANSMIT THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELE-
MENTS AFFECTED OR CONCERNED, THE RETRANSMITTAL SHALL REFERENCE THIS
MESSAGE.
DATA RECEIVED BY THIS COMMAND POINTS TO WIDE SPREAD POSSESSION
OF DEFECTIVE WINDOW PANELS. THESE ITEMS ARE DEFECTIVE BECAUSE OF THE
FOLLOWING CONDITIONS -
UNREMOVABLE PROTECTIVE COATING;
WINDOW HANDLES GLUED ONTO PANEL;

PAGE 2 RULNETC2156 UNCLAS
THESE DEFECTS PERTAIN TO PANELS DELIVERED ON CONTRACT DAAJ01-78-
-0531, SIGMA INDUSTRIES, INC.
IT IS REQUESTED THAT ALL PANELS DEFECTIVE DUE TO INABILITY TO
REMOVE PROTECTIVE COATING BE SHIPPED TO CORUS CHRISTI ARMY DEPOT
(COAD) MARKED FOR TSARCOM MISSION ACCOUNT.
PANELS DEFECTIVE FOR REASONS OTHER THAN REMOVAL OF PROTECTIVE
COATING SHOULD BE SCRAPPED (DISPOSE OF ONLY) IF DEFECTS CANNOT
BE RECTIFIED AT USER LEVEL.
POINT OF CONTACT (POC), THIS COMMAND, IS DENNIS MCGUIRE, AUTOVON
93-3738/3739 OR COMMERCIAL 1-314-3738/3739,

UNCLAS
2156

message
271701Z Feb 1980
faulty window