TECHNICAL BULLETIN Bell Helicopter

DATE

REV

No. SU-07-07

No. SU-07-07

Date May 2, 2007

Page 1 of 2

MODEL AFFECTED: UH-1H

SUBJECT: ALTERNATE SPARE PART; MAIN ROTOR PITCH

LINK ASSEMBLY 204-011-127-003

HELICOPTERS AFFECTED: UH-1H Helicopters which are non-type

certificated, owned and operated by other than

an Armed Service of the United States.

COMPLIANCE: At Customer's Option, use Main Rotor Pitch Link

Assembly P/N 204-011-127-003 as an alternate spare part in lieu of Main Rotor Pitch Link

Assembly P/N 204-011-127-001.

DESCRIPTION:

This Technical Bulletin provides authorization to UH-1H helicopter operators who wish to use Main Rotor Pitch Link Assembly P/N 204-011-127-003 as an alternate spare part in lieu of Main Rotor Pitch Link Assembly P/N 204-011-127-001. Main Rotor Pitch Link Assembly P/N 204-011-127-001 is currently used on the 205A-1 helicopter.

The following Retirement Life is applicable to Pitch Link 204-011-127-003.

Retirement Interval Item Part Number

9000 hrs Main Rotor Pitch Link 204-011-127-003

APPROVAL:

Not applicable. Bell Helicopter Textron does not authorize use of this bulletin to obtain approval from and Civil Regulatory Authority for installation of the alternate spare part on any type certificated helicopter.

TB SU-07-07 Page 2 of 2
WARRANTY:

Not applicable

MANPOWER:

Not applicable

SPECIAL TOOLS:

None required

WEIGHT AND BALANCE:

Not affected

ELECTRICAL LOAD DATA:

Not affected

REFERENCES:

Not applicable

PUBLICATIONS AFFECTED:

Technical Manual TM 55-1520-23P

ACCOMPLISHMENT INSTRUCTIONS:

Not affected. Installation and removal procedures remain unchanged.

Note

This Special Use Technical Bulletin must be inserted in the Helicopter Maintenance Manual upon bulletin accomplishment.