



Never do anything drastic—like grounding your bird—because of main rotor blade grip or pillow block oil discoloration.

Oil dark? Forget it! It's caused by wear of the O-ring packing and the dry film lubricant put on the yoke spindles.

Beads of water or other foreign contamination? Flush and refill next time the bird is down for maintenance.

