

TECHNICAL BULLETIN
Bell Helicopter
A Textron Company

No. SU-07-06
Date May 02, 2007
Page 1 of 2

DATE
REV

MODEL AFFECTED: UH-1H

SUBJECT: ALTERNATE SPARE PART; 42 DEGREE GEARBOX 212-040-003-023

HELICOPTERS AFFECTED: UH-1H Helicopters which are non-type certificated, owned and operated by other than an Armed Service of the United States.

COMPLIANCE: At Customer's Option, use 42 Degree Gearbox P/N 212-040-003-023 as an alternate spare part in lieu of 42 Degree Gearbox P/N 203-040-003-037.

DESCRIPTION:

This Technical Bulletin provides authorization to UH-1H helicopter operators who wish to use 42 Degree Gearbox P/N 212-040-003-023 as an alternate spare part in lieu of 42 Degree Gearbox P/N 203-040-003-037. The 212-040-003-023 Gearbox is currently used on the 205A-1 helicopter.

The following Time Between Overhaul (TBO) is applicable to 42 Degree Gearbox 212-040-003-023.

<u>Overhaul Interval</u>	<u>Item</u>	<u>Part Number</u>
5000 hrs	42 Degree Gearbox	212-040-003-023

APPROVAL:

Not applicable. Bell Helicopter Textron does not authorize use of this bulletin to obtain approval from and Civil Regulatory Authority for installation of the alternate spare part on any type certificated helicopter.

WARRANTY:

Not applicable

MANPOWER:

Not applicable

SPECIAL TOOLS:

None required

WEIGHT AND BALANCE:

Not affected

ELECTRICAL LOAD DATA:

Not affected

REFERENCES:

Not applicable

PUBLICATIONS AFFECTED:

Technical Manual TM 55-1520-23P

ACCOMPLISHMENT INSTRUCTIONS:

Not affected. Installation and removal procedures remain unchanged.

Note

This Special Use Technical Bulletin must be inserted in the Helicopter Maintenance Manual upon bulletin accomplishment.