

What do you think about using a larger washer on the Huey (UH-1D) connecting tube between the stabilizer bar and damper?

As I see it, the washer under the head of the attaching bolts is too small. A loose tube and bearing could ride over the washer and bolt—control of the bird would be lost.

Any suggestions?

MAJ J.H.P.

