

Looking for self-locking nuts that won't lose torque on the tail-rotor

Tail rotor drive-shaft

Use new

nuts

drive-shaft clamps of your Huey or Cobra?

Good news! The headshed has approved 2 non-slotted nuts in addition to slotted Nut NSN 5310-00-688-2069. You can now use "SPS-H19" and "VS". They both come under NSN 5310-00-702-5020.

Be sure not to mix different nuts on the same clamp.

You'll find the word in TSARCOM Msg DRSTS-MEA (2) 172010Z Nov 80.