

PRIORITY

OTUZEYX RULNNAC1288 1272815-0000--RUMMDTA.  
NR 00000

61743Z MAY 88 ZEX  
M MGR ARNG DAC EDGEWOOD MD //NGR-AVN-L//  
D AIG 7481

ARMY

61518Z MAY 88  
M CDRTSARCOM STC MO //DRSTS-NEA(2)//  
D AIG 8881  
NFO AIG 7514  
IG 7515  
IG 9884

UEOHZZ/US ENV PROT AGY REGION II 26 FEDERAL PLAZA NY NY  
UHNSSS/US ENV PROT AGY PO BOX 15227 LAS VEGAS NV OFC RSCH //  
EV ENV MONITORING AND SPT LAB/MOD//  
UEOLKA/NATIONAL OCEANIC AND ATMOSPHERIC ADM ROCKVILLE MD NOXA //  
A2 COL L A WEAVER//  
UCLBUA/CDRUSAAVNO FT RUCKER AL //ATZG-DI//  
UEHO/AIT WASH DC  
UEHIN/AIT TAIPEI TAIWAN  
UFLAFA/OJUSMG MAAG MADRID SPAIN //ARMY/NAVY SEC//

UH

T  
NO. 3  
OTE - THIS IS A MAINTENANCE ADVISORY MESSAGE AND HAS NOT, REPEAT  
AS NOT, BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES.  
ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL  
SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED.  
RE TRANSMITTAL SHALL REFERENCE THIS MESSAGE.

AGE 82 RUCIPRA5238 UNOLIS  
SUBJECT - CHANGE ONE (1) TO SAFETY-OF-FLIGHT MESSAGE (URGENT WITH  
IMITATIONS) ONE TIME INSPECTION OF ATTACHING HARDWARE OF LEVER  
SEMBLY P/N 41882257, NSN 1658-08-454-8915, OR P/N 41882265,  
SN 1658-08-229-6679, OR P/N 105881, NSN 1658-08-933-5539,  
R-P/N 105832, NSN 1658-08-928-3887, OR P/N 105827 (NSN NOT  
AVAILABLE) AS APPLICABLE. TB 55-1528-243-28-3 (AH-1-88-13,  
4-1-88-89)

CHANGE PARAGRAPH 8.C. TO READ -  
8.C. LIMITATIONS - DEPENDING ON AVAILABILITY OF PARTS AND  
DETERMINED BY THIS INSPECTION, THE FOLLOWING HARDWARE WILL BE  
CHANGED DURING THIS INSPECTION OR DURING THE NEXT SCHEDULED  
BASE INSPECTION:  
(1) NO CHANGE  
(2) NO CHANGE  
(3) SEE TB 55-1528-243-28-3 FOR CORRECT BOLTS, WASHERS, NUTS  
AND OTHER PIN INSTALLATION.  
FOREIGN MILITARY SALPS (FMS) INTERNATIONAL LOGISTICS RECIPIENTS  
SHOULD CONTACT CWS R. BROCK PATKINS, TSAROOM, DRSTS-IO, AUTOVON