

You say your Huey (UH-1B, D) engine fuel filter assembly, FSN 2915-011-1518, is clogged up with gunk and you need to put in a new filter?

Hold one before you order the whole filter assembly. The assembly was only for modification kits and it'll cost Uncle 100 smackers!

All you need is the \$3.37 replaceable filter element and the O-ring packings. These two items come in filter assembly repair kit, FSN 2945-019-0280, P/N 204-2490-1.

This kit can also be used to replace the external filter of the transmission oil system.

HERE'S		FSN	Item	Quantity
WHAT YOU)	(a)	5330-250-0236	Pecking	2
GET IN THE	(b)	5330-291-3078	Pecking	1
110	(c)	5330-618-1670	Packing	2
-	10	5330-726-4153	Packing	1
	(e)	P/N 204-040-760-13	Element	1

Use items c, d, and e when replacing the transmission oil filter element, and items a, b, and e on your engine fuel filter replacement jobs.

Where's this kit listed? Right in TM 55-1520-210-20P (Dec 66), fig 256 and fig 434 . . . in a special note, to boot!



