


Rollover Vent Valves

Dear Editor,

We've found that some of our UH-1s never had fuel tank rollover vent valves installed per MWO 55-1520-210-30-43.

It's easy to check. Just open the fuel filler cap and look for a valve in the top of the right hand aft fuel cell. Please pass the word.



Check here for valve

**Shawn Carey
Windsor Locks, CT**

(Editor's note: The word's out. Units that have UH-1s without rollover vent valves should report it in writing to:

*Cdr, AVSCOM
ATTN: AMCPM-UH-1
4300 Goodfellow Blvd
St Louis, MO 63120-1798)*