

CAL NATL GRD
RR 910-367-3543 V 510-765-6678 NR035A 02AUG79/DOD
R-011948Z AUG 77 ZEX

FM MGR ARNG OAC EDGEWOOD W57/NGB-AVN-L//
TO RUVN555/CG CA NG SACRAMENTO CA/
RUEPNHC/TAG CT HARTFORD CT
RUVRBGA/TAG MS JACKSON MS
RUCCDNJC/TAG MO JEFFERSON CITY MO
INFO RUVMBEA/TARS CA FRESNO CA
RUEDBJB/TARS CT GROTON CT
RUWTSUC/TARS MS GULFPORT MS
RUWTAHR/TARS MO SPRINGFIELD MO
RUEAUSA/CNGB WASH DC//NGB-ARL-A//
BT

2
R

ACTION: SAO
USPFO (TWX)
INFO:
:
:

UNCLAS
PROVIDE COPY TO USPFO
SUBJ PREREQUISITE FOR APPLICATION OF MWO 55-1520-210-30-54,
PROVISIONS FOR INSTL OF KAFLEX MAIN DRIVE SHAFT (INSTL OF
BLEED AIR PARTICLE SEPARATOR)
A. MGR ARNG OAC NGB-AVN-L 011540Z JUL 79 SAB.
THIS MESSAGE IN TWO PARTS
PART ONE FOR TARS

K-flex

PAGE 2 RULNNAC1995 UNCLAS

1. REF A INDICATED THAT THE SELF-PURGING PARTICLE SEPARATOR WAS REQUIRED AS A PREREQUISITE TO INSTL OF MWO 55-1520-210-30-54 PROVISIONS FOR THE INSTL OF KAFLEX MAIN DRIVE SHAFT AND REQUESTED A REPORT TO DETH THE NUMBER OF PARTICLE SEPARATORS REQUIRED.
2. FUNDING HAS BEEN PROVIDED TO THE TARS IN ORDER TO INSURE COMPLETE INSTL FOR ACFT WITHIN THEIR SPT AREA. AS ACFT CONFIGURATION MAY VARY, DEVIATION FR THE COMPONENT LIST IS AUTH.
3. TYPICAL COMPONENT LISTING, REF TM 55-1520-210-23P-1, 1 MAR 77, FIG 111, PAGE 559.

ITEM	NOMENCLATURE	NSN/PN	QTY
2	AIR FILTER UPPER	2945-00-442-2544 1-010-420-05	1
15	AIR FILTER LOWER	2945-00-442-2539 1-010-360-05	1
14	GASKET ASSY	5330-00-455-9704 1-010-530-03	2
24	GASKET	5330-00-456-8042	1
30	CLEANER AIR	2945-00-442-2555 1-300-499	1

4. ADDITIONAL COMPONENTS MAY BE REQUIRED IF MWO 55-1520-210-30/29, PROVISIONS FOR BLEED AIR LINE PARTICLE SEPARATOR HAS NOT BEEN FULLY

PAGE 3 RULNNAC1995 UNCLAS
COMPLIED WITH.

PART TWO FOR TARS STATE USPFO

5. AS THE RESULT OF A CHANGE IN FUNDING ON THE FOL ITEMS FR STOCK FUND TO PA FUNDS, MONIES ALLOCATED TO THE TARS FOR THE PARTICLE SEPARATORS MAY BE EXCESSIVE CLN

A. AIR FILTER UPPER 2945-00-442-2544 \$904 EACH
B. AIR FILTER LOWER 2945-00-442-2539 \$1,134 EACH

6. FUNDS EXCESS TO PARTICLE SEPARATOR REQUIREMENTS ARE AVAILABLE FOR REPROGRAMMING WITHIN TARS ACCOUNTS

46

2 Mar 79 19 59z

main drive shaft

ARMY

ROTEZYUW RULNNAC0557 0611729-EEEE--RUKMDTA;
ZNY EEEEE
R 021701Z MAR 79
FM ARNG OPERATING ACTIVITY CENTER//NGB-AVN-L//
TO AIG 7401
R 011925Z MAR 79
FM CDRTSARCOM STL HQ//DRSTS-SAJA(2)//
TO AIG 8879
INFO AIG 9004

BT
UNCLAS E F T O
NOTE: THIS IS A SUPPLY ADVISORY MESSAGE AND HAS NOT,
REPEAT, HAS NOT, BEEN TRANSMITTED TO UNITS SUBORDINATE
TO ADDRESSES; ADDRESSES SHOULD IMMEDIATELY RETRANSMIT
THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR
ELEMENTS AFFECTED OR CONCERNED;
SUBJ: NSN 1615-21-238-9968, MAIN DRIVESHAFT, UH-10/H,
UH-1H

1. THE PURPOSE OF THIS MESSAGE IS TO CLARIFY THE
PROVISIONS OF MWO 59-1628-218-32-54, PARA 8E OF THE
MWO IS NOT TO BE INTERPRETED AS A REQUIREMENT FOR AUTO-
MATIC REPLACEMENT OF THE DRIVESHAFT. THE DRIVESHAFT
WILL NOT BE REPLACED EXCEPT ON AN ATTRITION BASIS. THE
REMOVED DRIVESHAFT WILL BE REINSTALLED IF IT IS IN A
SERVICABLE CONDITION;

PAGE 2 RULNNAC0557 UNCLAS E F T O
2. REQUISITIONS FOR THE SUBJECT DRIVESHAFT SHOULD BE
SUBMITTED ONLY TO REPLACE UNSERVICABLE DRIVESHAFTS;
ALL CURRENT DUES-OUT FOR THIS DRIVESHAFT ARE BEING
CANCELLED BACK TO THE REQUISITIONER SINCE IT APPEARS
THAT REQUISITIONS ARE BEING SUBMITTED TO COVER ONE HUND-
RED PERCENT REPLACEMENT;
3. POC THIS COMMAND IS MR. HARVIN CASPERSEN, AUTOVON
698-2027, COMMERCIAL 314-248-2027;

BT
#0557

18

46

NNNN