

CORRECTED COPY

Sube oil
Gen-76-02

22 JAN 76 23 49Z

RATUZELX RULNEAA0475 022211Z UUUU--RUWMDTA;
ZNR UUUUU
R 222100Z JAN 76 ZEX ZEL,FM CDR ARNG-DAC EDGEWOOD MD //DAC-AVN-L//
TO AIG 7401
R 221428Z JAN 76 ZEX
FM CDRAVSODM STL MO //AMSAV-FEP//
TO AIG 8881

ARMY

BT
UNCLAS
NOTE CLN THIS MESSAGE HAS NOT, REPEAT, HAS NOT BEEN TRANSMITTED TO
UNITS SUBORDINATE TO ADDRESSEES, ADDRESSEES ARE RESPONSIBLE
FOR DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS,
ACTIVITIES, ELEMENTS, OR FOREIGN USERS AFFECTED OR CONCERNED;
RETRANSMITTAL SHALL REFERENCE THIS MESSAGE;
SUBJ CLN MAINTENANCE ADVISORY MESSAGE ON AIRCRAFT LUB OIL,
CONTINENTAL MOTORS SPEC, MHS24A (GEN-76-02)
1. DGSC HAS EXCESSIVE STOCKS OF SUBJECT PRODUCT WHICH WERE PROCURED
TO SUPPORT ARMY T-41 AND T-42 AIRCRAFT, OF WHICH FORECASTED DEMANDS
HAVE NOT MATERIALIZED, PRODUCT IS ACCEPTABLE SUBSTITUTE FOR MIL-L-
22851, LAD OILS, AND PERMISSION HAS BEEN GRANTED DGSC TO SUBSTITUTE
PAGE 2 RULNEAA0475 UNCLAS
ON QUART CAN RONS AS FOLLOWS CLN
A. ORDERS RECEIVED FOR NSN 9150-00-168-6889, ONE QT, CAN OF
MIL-L-22851, TYPE II, WILL BE SUBSTITUTED WITH NSN 9150-00-412-2066
ONE QT, CAN OF MHS24A, GRADE 30,
B. ORDERS RECEIVED FOR NSN 9150-00-219-5701, ONE QT, CAN OF
MIL-L-22851, TYPE III, WILL BE SUBSTITUTED WITH NSN 9150-00-412-2065,
ONE QT, CAN OF MHS24A, GRADE 40,
2. ALL AFFECTED PERSONNEL SHOULD BE ALERTED AND BRIEFED RELATIVE
TO THE ABOVE SUBSTITUTION AUTHORIZATION, CAUTION ALL ORDERING
ACTIVITIES TO CONTINUE REQUISITIONING THE NSNS FOR MIL-L-22851,
LAD OILS, DGSC WILL AUTOMATICALLY SUBSTITUTE UNTIL STOCKS OF
MHS24A ARE NORMALIZED,
3. POINT OF CONTACT - MR. ROBERT M. FETCH, AMSAV-FEP,
AUTOVON 698-5356 OR 314-268-5356,
BT

0475

10
3