

**TECHNICAL BULLETIN**  
**Bell Helicopter** **TEXTRON**

A Subsidiary of Textron Inc.

No. SU-94-2

Date 5-23-94

Page 1 of 2

DATE 9 Jan 2007

REV A

Distribution A: Approved for Public Release IAW DOD Memo 07-S-0964

**MODEL AFFECTED:** UH-1H

**SUBJECT:** ALTERNATE SPARE PART; Tail Rotor Blade P/N  
204-011-702-121

**HELICOPTERS AFFECTED:** UH-1H Helicopters which are non-type  
certificated, owned and operated by other than  
an Armed Service of the United States.

**COMPLIANCE:** At Customer's Option, use Tail Rotor Blade P/N  
204-011-702-121 as an alternate spare part in  
lieu of Tail Rotor Blade P/N 204-011-702-015.

**DESCRIPTION:**

This Technical Bulletin provides authorization to UH-1H helicopter operators who wish to use Tail Rotor Blade P/N 204-011-702-121 as an alternate spare part in lieu of Tail Rotor Blade P/N 204-011-702-015. The 204-011-702-121 Blade is currently used on 204B helicopters. The -121 blade is painted gloss white with three bands of gloss black, whereas the -015 blade is painted lusterless olive drab.

**APPROVAL:**

Not applicable. Bell Helicopter Textron does not authorize use of this bulletin to obtain approval from any Civil Regulatory Authority for installation of the alternate spare part on any type certificated helicopter.

**MANPOWER:**

Not applicable

**MATERIALS:**

None Required

**SPECIAL TOOLS:**

Not applicable

**WEIGHT AND BALANCE:**

Not affected

**ELECTRICAL LOAD DATA:**

Not affected

**REFERENCES:**

Technical Manual TM 55-1520-210-23-1, Chapter 5

**PUBLICATIONS AFFECTED:**

Technical Manual TM 55-1520-210-23P-1, Figure 147

**ACCOMPLISHMENT INSTRUCTIONS:**

Not affected. Installation and removal procedures remain unchanged.

**Note**

**This Special Use Technical Bulletin must be inserted in the Helicopter Maintenance Manual upon bulletin accomplishment.**