AHA--THE MISSING LINK!



Paste this reminder in the back of your noggin before you heave-ho on your Huey (UH-1) main rotor hub and blade assembly.

After you remove the pitch links, put in the grip-positioning links to hold the grips and blades in position . . . prevents damage to the hub straps—for real!!

Use link, T101348, for the A Model, T101402 for the B and D Models, and T101466 for the C Model.

