


TM 55-1730-225-23P has hit the field housing assembly-swivel wheel with the repair parts for your aircraft included-and slip it right into the tow bar, NSN 1730-00-967-9556.

tube of a broken tow bar.





From then on, just ask for wheel replacements.



One point, tho. The new wheel won't fit an old housing with its non-, swiveling wheel. So the way to go, at wheel replacement time, is with a new housing.

Keep 'em rolling...with the right replacement parts!

