

OK! THAT SUMS UP THE BASIC PROBLEM!
THE SOLUTION IS FOR TROOPS FLYING IN
CHOPPERS, FOR AIRCRAFT MECHS MAINTAINING
AIRCRAFT AND FOR TROOPS SERVICING AIRCRAFT
TO **ALWAYS** AVOID THE USE OF

BRUTE FORCE

FOR EXAMPLE, THE
HUEY FLOOR IS A
HONEYCOMB
PANEL.

TROOPS SHOULD NEVER THROW OBJECTS ON THE FLOOR
WHICH CAN PUNCTURE THE FLOOR PANEL. THIS WILL LEAD
TO EARLY REPLACEMENT.

AIRCRAFT MECHS
SHOULD NOT
THROW TOOL
BOXES ON THE
ENGINE DECK—
ANOTHER HONEY-
COMB PANEL. THIS
CAUSES VOIDS IN
THE DECK—MORE
EARLY REPLACEMENT.
IT'S OK TO
PLACE THE TOOL
BOX ON THE DECK.