


Addendum to H-60-09-ASAM-04 / UH-1-09-ASAM-01  
**MK44 MOD 0 Cartridge Activation Device**

**CORRECT INSTALLATION**

**BRASS COLLAR REMOVED**



**INCORRECT INSTALLATION**

**BRASS COLLAR INSTALLED**

