

PAGE 03 ENCIFROSD18 UNCLAS

NOTE - THIS IS A SAFETY OF FLIGHT MESSAGE AND HAS NOT, REPEAT, NOT BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES.

ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED. THE RETRANSMITTAL SHALL REFERENCE THIS MESSAGE. ACTION ADDRESSEES WILL IMMEDIATELY VERIFY THIS RETRANSMISSION TO, COMMANDER, AVSCOM, ATTN - WMSAV-MEN.

REF: TM 55-1520-210-23

1. SUMMARY OF PROBLEM -

A. SUBSEQUENT TO DELIVERY TO THE GOVERNMENT OF A LOT OF 196 COLLECTIVE LEVER ASSEMBLIES, IT WAS DETERMINED THAT THE FLASHING WAS NOT SATISFACTORILY REMOVED TO MEET QUALITY ASSURANCE AND ENGINEERING STANDARDS. STRESS RISERS CAN OCCUR IN THE LEVER IF NOT PROPERLY MACHINED.

B. THIS MESSAGE IS ALSO TO ADVISE USING UNITS THAT SERVICEABLE COLLECTIVE LEVERS EJM 210-010-407-3, AUTHORIZED FOR USE ON UH-109A/109-1 HELICOPTERS, HAVE AN UNLIMITED FATIGUE LIFE, AND THEREFORE NO SA FROM 2410 IS REQUIRED.

2. PRIORITY CLASSIFICATION -

W - AIRCRAFT IN SERVICE - DESERT WITH LIMITATIONS - UPON RECEIPT

PAGE 04 ENCIFROSD18 UNCLAS

AT THIS MESSAGE ALL CIRCLED AIRCRAFT WILL BE CHANGED TO A CIRCLE AND 2410 STATUS. ALL UH-109A/109-1 SERIES AIRCRAFT WILL BE INSPECT

ED TO DETERMINE IF THE COLLECTIVE LEVER ASSEMBLIES CITED IN PARAGRAPH 1 WERE INSTALLED. WHILE AIRCRAFT ARE CARRIED ON CIRCLE AND 2410 STATUS, PARTIALLY MISSION CAPABLE (PMC) REPORTING REQUIREMENTS OF WP 45-11 ARE VALID. THE ORDER APPLIED TO CONTENTS OF THIS MESSAGE ONLY.

1. AIRCRAFT FOUND WITH COLLECTIVE LEVERS INSTALLED, OTHER THAN THOSE CITED IN THIS MESSAGE, THAT ARE STILL SERVICEABLE WILL IMMEDIATELY BE RELEASED FROM THE REQUIREMENTS OF THIS MESSAGE.

2. AIRCRAFT IN DESERT STOCK - AIRCRAFT WILL NOT BE ISSUED UNTIL THIS MESSAGE IS COMPLIANT WITH:

1. AIRCRAFT UNDERGOING MAINTENANCE - MAINTENANCE ACTIVITIES

1.1. UNDER 100 HOURS WILL COMPLY WITH MESSAGE

2. AIRCRAFT IN TRANSIT -

2.1. AIRCRAFT VIA SHIPMENT - INSPECT AT FINAL DESTINATION.

2.2. AIRCRAFT VIA AIR - INSPECT WITHIN 30 FLIGHT HOURS/10 DAYS.

3. PARTIALLY MISSION CAPABLE (PMC) AIRCRAFT - INSPECT WITHIN PRE-

SCRIBED TIME LIMITS.

4. AIRCRAFT IN STOCK AT ALL LEVELS - REMOVE FROM STOCK AND

PAGE 05 ENCIFROSD18 UNCLAS

1.1.1. MANUFACTURER IN COMPLIANCE WITH THIS MESSAGE

THE ITEMS TO BE INSPECTED - ALL UH-109A/109-1 HELICOPTERS

COLLECTIVE LEVER ASSEMBLIES TO BE INSPECTED - COLLECTIVE LEVER ASSEMBLIES

EJM 210-010-407-3, NSN 1410-00-471-0418, SAH SA 001 THROUGH EA

194

1.1.2. AIRCRAFT TO BE INSPECTED - NOT APPLICABLE

1.1.3. AIRCRAFT TO BE INSPECTED - NOT APPLICABLE

1.1.4. AIRCRAFT TO BE INSPECTED - NOT APPLICABLE

1.1.5. AIRCRAFT TO BE INSPECTED - NOT APPLICABLE