

SEC MSG # TIME RI
05646 2324 108/AS

IMMEDIATE

ZJ08NV 240TH 453FTS 2CAF AERO ACO ACP ADC ACE DET ADG/CC FTW/CC AUDITOR
CAP COM COMSEC DAPD W/DO D9J D99C D99S D9TM DPC DPH FC FCS
JA LCC LGS LCT MA NAVY NCAW OSI OT PA SE SC SS SSF SV T/A WEA XPMT XPR

CTUZEXN RULHEA6662 1082320 (UUU) - RUMROTA.

NR UUUUU

182300Z APR 85 ZEX
FM ARMG OAC AFG MD //HGB-AVM-L//
TO AIG T401

(22) ARMY

ULLSXN/TAG VI CHRISTIANSTED ST CROIX VI

ACCT DA-BHCSVD

C 182010Z APR 85

FM CDRAWSCOM STL MO //ANSAY-N//

TO AIG 8851

RUEHPO/US EMBASSY ROME ITALY //ODC/ PASS TO HQ MFO//

RUECLFA/US EVR PROT AGY PO BOX 13027 LAS VEGAS NV

RUECLYFA/US EVR PROT AGY REGION II 20 FEDERAL PLAZA NY NY

RUELEBA/CDRUSAVMC FT RUCKER AL //ATZA-DI-AQ//

//FOR MOAB HELICOPTER GROUP//

RUEHIN/AIT TAIPEI TAIWAN

RUEHC/AIT WASH DC

RUEFLAE/USDOCO LANDSOUTHEAST IZMIR TU //AV//

RUEHNS/COMUSMILGP SAN SALVADOR EL SALVADOR //SCES-AF//

RUEBDNA/COMJTF-B COMAYAGUA HO //E//

RUESSBG/COMUSMILGP BOGOTA COLUMBIA //SCCD-AFDCN//

RUCDQDA/COMCOM REDSTONE ARS AL //ANSMI-ST//

RUEATRS/US CUSTOMS SERVICE DEPT OF TREASURY WASH DC

MFO AIG 9004

AIG 7515

RUEHIV/USDAO TEL AVIV ISRAEL

RUEHC/SECSTATE WASH DC //HEA/MFO//

RUEOPHA/DISC PHILADELPHIA PA //OEBB-JU//

*UH-1-85-off
clam fab space
elevators*

PAGE 02 RUCIFR0662 UNCLAS

RUEHDT/COMSMAC BANGKOK THAILAND

RAYAAC/HQSCLOGEN MELBOURNE AUSTRALIA //S0AIRENG//

RAYMPP/DEFAIR TECH CANBERRA AS //DAIRENG-AF/9RHEL-AF//

RUEAKKE/AUSTRALIA WASHINGTON DC //SENGSO//

RUEVDFL/USDA FOREST SERVICE PO BOX 2417 WASH DC

//COOPERATIVE FIRE PROTECTION//

RCCPCLA/LOG CON OTTAWA CANADA //DTHM 4-2//

ACCT DA-BHCSVD

BT

UNCLAS

SECTION 01 OF 02

SUBJECT - SAFETY OF FLIGHT, TECHNICAL MESSAGE, ONE TIME INSPECTION
OF ALL UH-1D/H/V AND EH-1 SERIES AIRCRAFT FOR CHEN FAB LEFT AND RIGHT
HAND ELEVATOR ASSEMBLIES P/N'S 205-030-856-19 AND 205-030-856-21.

(UH-1-85-04) (TO 35-1520-242-20-14)

TASKING COMPLIANCE SUSPENSE DATE - 10 DAYS

NOTE - THIS IS A SAFETY OF FLIGHT, TECHNICAL MESSAGE, RELEASED IN
ACCORDANCE WITH AR 95-1A, DATED 1 MAY 1980. THIS MESSAGE HAS NOT,
REPEAT, HAS NOT BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES.
ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL

U-4

PAGE 03 RUCIFR06662 UNCLAS

SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED. THE RETRANSMISSION SHALL REFERENCE THIS MESSAGE. ACTION ADDRESSEES WILL IMMEDIATELY VERIFY THIS RETRANSMISSION TO COMMANDER, AVSCOM, ATTN - MSAY-MEM.

A. TM 55-1520-210-23 AVIATION UNIT AND INTERMEDIATE MAINTENANCE MANUAL AND INSTRUCTIONS ARMY MODEL UH-10/H/V/EH-1H HELICOPTERS DATED 20 FEB 79.

1. SUMMARY OF PROBLEM -

A. CERTAIN RIGHT AND LEFT ELEVATOR ASSEMBLIES EXHIBIT AN OUT OF RIG CONDITION WHEN INSTALLED ON THE AIRCRAFT. THUS THEY CANNOT BE ADJUSTED, RIGGED, OR RERIGGED BY SHIMMING TO MEET INSTALLATION REQUIREMENTS OF REF A.

B. PURPOSE - IT IS THE PURPOSE OF THIS MESSAGE TO INSPECT AND REMOVE THESE ELEVATOR ASSEMBLIES FROM USE AND ALL LEVELS OF STOCK.

2. PRIORITY CLASSIFICATION -

A. AIRCRAFT IN SERVICE - URGENT WITH LIMITATIONS. UPON RECEIPT OF THIS MESSAGE ALL CITED AIRCRAFT WILL BE CHANGED TO A CIRCLE RED //X//. ALL UH-10/H/V/EH-1 SERIES AIRCRAFT WILL BE INSPECTED TO DETERMINE IF THESE RIGHT OR LEFT ELEVATORS ARE INSTALLED. WHILE AIRCRAFT ARE CARRIED IN CIRCLE RED //X// STATUS PARTIALLY MISSION

PAGE 04 RUCIFR06662 UNCLAS

CAPABLE (PMC) REPORTING REQUIREMENTS OF AR 95-33 ARE WAIVED. THE WAIVER APPLIES TO CONTENTS OF THIS MESSAGE ONLY.

(1) SHOULD THESE ELEVATORS BE INSTALLED THE AIRCRAFT STATUS WILL BE UP GRADED TO A RED //X// UNTIL THE CHEM FAB ELEVATORS ARE EMAYED.

(2) AIRCRAFT FOUND WITH OTHER THAN CHEM FAB ELEVATORS WILL IMMEDIATELY BE RELEASED FROM THE INSPECTION AND GROUNDING REQUIREMENTS OF THIS MESSAGE.

B. AIRCRAFT IN DEPOT STOCK - ROUTINE SERVICEABLE AIRCRAFT IN DEPOT STOCK WILL BE INSPECTED AS SOON AS PRACTICAL. AIRCRAFT WILL NOT BE ISSUED UNTIL INSPECTED.

C. AIRCRAFT UNDERGOING MAINTENANCE - MAINTENANCE ACTIVITIES PERFORMING SUCH MAINTENANCE.

(1) SURFACE AIR SHIPMENT - INSPECT AT FINAL DESTINATION.

(2) FERRY STATUS - INSPECT AS SOON AS PRACTICAL.

D. MAINTENANCE TRAINER (CATEGORY A, B) INSPECT WITHIN PRESCRIBE

3. TIME LIMITS.

E. COMPONENTS IN STOCK AT ALL LEVELS - THE ELEVATOR ASSEMBLIES RIGHT AND LEFT HAND WILL BE REMOVED FROM STOCK AND RETURNED TO MANUFACTURER IN ACCORDANCE WITH THIS MESSAGE.

PAGE 05 RUCIFR06662 UNCLAS

2. END ITEMS TO BE INSPECTED - ALL UH-10/H/V/EH-1 HELICOPTERS.

3. ASSEMBLY COMPONENTS TO BE INSPECTED - LEFT HAND ELEVATOR ASSEMBLY P/N 205-030-856-19, NSN 1560-00-996-3906, S/N 0001 THROUGH 0158 AND RIGHT HAND ELEVATOR ASSEMBLY P/N 205-030-856-21, NSN

560-00-996-3905, S/N 0001 THROUGH 0146.

4. PARTS TO BE INSPECTED - NOT APPLICABLE.

5. APPLICATION -

A. THIS INSPECTION MAY BE PERFORMED BY UNIT MAINTENANCE PERSONNEL.

B. TIME REQUIRED -