



**2 WILL DO!**

LUBE FITTING

Over lubing your Huey's tail rotor crosshead bearing spells d-a-n-g-e-r.

Your Huey's dash 20 says it gets 2 handgunned shots—and only 2—of GAP lube every Periodic.

An overdose of MIL-G-22537 here will pop the T/R gear-box seal, and a busted seal means you'll be mixing gear-box lube oil with grease. That's not the way to win a ball game.

So-o-o-o, when you're PMP-ing your Bird Beautiful the bearing gets 2 shots—no more, no less.

BETTER MAKE IT TWO.

THAT'S A SHOT IN THE TAIL.