

*incorrect UH-1-75-19  
servo P/N  
2943- COOK*

*ARMY*

PTTUZEYN RUEDACA0599 3231600-UUUU--RUKMDTA;  
ZNR UUUUU  
P R 191310Z NOV 75 ZEX  
FM ARNG OPERATING ACTIVITY CENTER EDGEWOOD ARSENAL MD//DAO-AVN-L//  
TO AIG 7481  
INFO RUEFHQA/CNQR WASHDC//NGB-AHL-A//  
P R 181718Z NOV 75 ZFF-1  
FM CDRUSAAVSCOM STL MD//AMSAV-FEU//  
TO AIG 8581  
INFO AIG 9584  
RUMTAPA/CDRUSABPA FT WORTH TX//SAVBE-E//  
RUODDDA/CDRUSABAFSCOM HUNTSVILLE AL  
RUOLDGA/CDRUSAAVNG FT PUCKER AL  
BT  
UNCLAS

NOTE CLN THIS IS A MAINTENANCE ADVISORY MESSAGE AND HAS NOT OMM REPEAT HAS NOT OMM BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES; ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL SUBORDINATE UNITS OMM ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED, THE RETRANSMITTAL SHALL REFERENCE THIS MESSAGE, SUBJECT CLN MAINTENANCE ADVISORY MESSAGE FOR UH-1H AIRCRAFT OMM EN UH-1-75-19 PAREN.

PAGE 2 RUEDACA0599 UNCLAS  
1, PURPOSE OF MESSAGE CLN TO MAKE USERS AWARE OF AN INCORRECT ENTRY IN THE AIRCRAFT FORMS OF A SERIES OF UH-1H AIRCRAFT DELIVERED BY BELL HELICOPTER COMPANY AND TO PROVIDE INFORMATION FOR A CORRECTING ENTRY.  
2, PROBLEM CLN BHC HAS ADVISED THAT 244 AIRCRAFT OMM SERIAL NUMBERS INDICATED BELOW OMM HAVE ENTRIES ON THE DA FORM 2418 INDICATING INSTALLATION OF A HYDRAULIC SERVO CYLINDER ASSEMBLY WHICH IS NOT THE ASSEMBLY ACTUALLY INSTALLED, THE AFFECTED AIRCRAFT ARE AS FOLLOWS CLN  
UH-1H S/N 72-21649  
UH-1H S/N 72-21838 AND SUBSEQUENT;  
WHEN THE AIRCRAFT WERE RELEASED BY BHC TO THE USER THE DA FORM 2418 REFLECTED THAT THE INSTALLED SERVO CYLINDER ASSEMBLY WAS P/N 285-876-038-7 OMM NSN 1658-02-183-4426, BHC HAS ADVISED THAT THE AIRCRAFT ACTUALLY HAD RECEIVED P/N 285-876-899-7 OMM NSN 1658-02-148-9877;  
3, ACTION REQUIRED CLN ORGANIZATIONS HAVING ANY OF THE INDICATED AIRCRAFT SHOULD CHECK THE DA FORM 2418 AGAINST THE SERVO CYLINDER ASSEMBLY ACTUALLY INSTALLED AND CORRECT THE FORM 2418 AS NECESSARY; THE NAMEPLATE IDENTIFYING THE SERVO CYLINDER ASSEMBLY IS LOCATED ON THE RIGID CONNECTING LINK CONNECTING THE HYDRAULIC SERVO

*123*

3 RUEDAQA2599 UNCLAS  
CYLINDER TO THE SWASHPLATE;  
PT  
#0599

NNNN